

Mackenzie Hoy Consulting **Acoustics Engineers** 

Leaders in African Acoustics

5 Coniston Way, Pinelands, 7405 Cape Town, South Africa www.machoyrsa.com

Tel: + 27 (0)21 424 5719 Fax: + 27 (0)21 531 3334 Email: machoy@iafrica.com

> 15th March 2017 Rev 2

## **Ashlea Strong Principal Consultant**

WSP | Parsons Brinckerhoff, Environment & Energy, Africa WSP House, Bryanston Place, 199 Bryanston Drive, Bryanston, 2191, South Africa Tel: +27 11 361 1392 | Mobile: +27 82 786 7819 | Fax: +27 11 361 1381 | www.wsp-pb.com

## Maralla East Wind Energy Facility : Acoustic Impact Assessment: Peer Review

1. Introduction

This document is a peer review of an acoustic impact assessment report for the Maralla East Wind Energy Facility of Biotherm Energy Pty Ltd. The report is compiled by WSP / Parsons Brinckerhoff.

The findings of this Acoustic Impact Assessment: Peer Review are summarised as follows:

- a. Daytime and night-time noise monitoring of existing noise climate is inadequate.
- b. There are calculation errors of a minor nature in the document.
- c. Noise contour plots are inadequately labelled.

T.E. Mackenzie-Hoy Pr. Eng. Bsc (Elec) M.S.A.I.E.E., M.S.P.E., IngP (Eur), AmASA (Director)T. Tanzer BSc (Mech), Rachel Viljoen BEng (Mechatronics), M. Attwood (Adv Dip S.Eng), G. Meredith ND (Elec) T. Matora BSc (Mechatronics)

- 2. Detailed Examination Of Acoustic Impact Assessment Document
  - a. To determine the existing residual level reference should be made to para 5.1.6.2 of SANS 10103. From this it can be seen that at every receptor/farm house at least a 24-hour measurement should be made of noise levels. It will be further prudent to break up the measurements into averages over 10 minutes and to present these graphically with the 24-hour measurement. It is not accurate to do measurements lasting less than 24 hours.
  - b. Ad Para: Existing Noise Climate
    - It is evident from Table 10 (page 29) that the details of item (iii) above have been ignored. The table lists measurements made at farmhouses 1, 2, and 3.
      - The measurements are taken at three times during the day. No indication is given how long the measurements were taken for. This is inadequate for the measurement of residual levels.
      - In the column headed LAeq a value is given. The term LAeq is the equivalent continuous sound pressure level over a period of time. There is no indication of what period of time applied to the measurements.
      - Refer to para 5.1.4 and 5.1.6.2 of SANS 10103.
      - In the column headed L<sub>A90</sub> a daytime average is given. For all measurements at farmhouses 1, 2 and 3 the average is incorrectly calculated - the averages have been calculated as arithmetical averages when in fact they should be calculate as logarithmic averages.

T.E. Mackenzie-Hoy Pr. Eng. Bsc (Elec) M.S.A.I.E.E., M.S.P.E., IngP (Eur), AmASA (Director)T. Tanzer BSc (Mech), Rachel Viljoen BEng (Mechatronics), M. Attwood (Adv Dip S.Eng), G. Meredith ND (Elec) T. Matora BSc (Mechatronics)

- ii. By not calculating a correct value for LAeq it is impossible to proceed with analysis of the effect of the noise on the farmhouses.
- iii. On page 26 the last paragraph indicates that "sound level monitoring could not be undertaken during the night-time timeframe" due to "safety considerations at the night". One presumes that since the measurements were made at farmhouses and that a farmhouse is a reasonably secure location it should be quite easily possible to undertake night-time monitoring. It would simply be a matter of installing the sound level meter at the farmhouse and sitting at a record for a night with collection and download of data the following day. It is almost inconceivable that a noise Impact assessment can be undertaken without data for night-time or, more importantly, early morning.
- c. Ad para 4 : Findings
  - i. On none of the noise contour maps showing noise levels at given wind speeds is the windspeed direction given.

Yours sincerely,

Mackenzie Hoy

T.E. Mackenzie Hoy Pr. Eng Bsc( Elec ) Registered professional engineer number 840428 for: Mackenzie Hoy Consulting Engineers