

EXTERIOR FACADE



93 MANOR VIEW ROAD, BELLAIR

EXTERIOR FAÇADE- ILLUSTRATING TIN WALL STRUCTURE AND BROKEN AWNINGS





93 MANOR VIEW ROAD, BELLAIR



EXTERIOR FAÇADE- ILLUSTRATING TIN ROOF AND BROKEN GUTTERS











EXTERIOR FAÇADE- ILLUSTRATING TIN WALL STRUCTURE THAT IS ERODED AND TIMBER WALL SUPPORTS INFESTED WITH WOOD BORERS



EXTERIOR FAÇADE- ILLUSTRATING TIN WALL STRUCTURE THAT IS ERODED AND TIMBER WALL SUPPORTS INFESTED WITH WOOD BORERS





FRONT STOEP SHOWING THE CRACKED CONCRETE BASE



EXTERIOR FAÇADE- ILLUSTRATING TIN WALL STRUCTURE THAT IS ERODED AND TIMBER WALL AND FLOOR SUPPORTS ARE INFESTED WITH WOOD BORERS





DAMPNESS FROM THE ROOF HAS ENTERED THE HOUSE AFFECTING THE HEALTH AND SAFETY OF THE HABITANTS





CRACKED CONCRETE FLOOR SLABS





DAMPNESS FROM THE ROOF HAS ENTERED THE HOUSE AFFECTING THE HEALTH AND SAFETY OF THE HABITANTS





DAMPNESS FROM THE ROOF HAS ENTERED THE HOUSE AND HAS AFFETED THE STRUTUAL INTEGRITY OF THE TIMBER WALL STUDS





















THE DAMPNESS IN THE CRAWL SPACE HAS FOSTED MOULD GROWTH WHICH IS A HEALTH AND SAFTEY CONCERN FOR THE HABITATS





THE DAMPNESS IN THE CRAWL SPACE HAS STRUTURALLY AFFECTED THE TIMBER SUPPORTS FOR THE FLOOR AND THE TIMBER IS AFFECTED WITH WOOD BORERS

