

Archaeological Site Report	SiteNo	9/2/003/0064
	Site Name	Mooimeisiesfontein, Riebeeck East, Albany District
	Date	07/06/1996 - 09:24
	Project	
	CaseNID	
	Coords	-33.199504, 26.167020

Page No: 1 **SiteAutoID:** 71

Site Category: Building

SiteComments:

The following report and attached photographs are submitted for your information: Only the exterior of the building was inspected. All in the property is in good condition. However, there are certain reasons for concern: Photo 1: Shows damage to the guttering and facias, on the front facade. Photo 2: Shows damaged caused by a leaking geyser to the rear of the facade. Photo 3: Shows the northern wall to the outbuilding. Photo 4: Shows the front facade. Photo 5: shows the southern gable of the building. Photo 6: Shows the view from the front facade. It would appear the NMC property extends to the bush line in the rear of the photo, possibly further. As one can see there are two windmills in the photograph, one is very dilapidated, According to Mr Buise both were like that and he repaired one. The river running alongside the property is more or less dry.

AdminComments:

Photographs from 1996 inspection are required

Damage Types: