

<b>Archaeological Site Report</b>	<b>SiteNo</b>	AMA051
	<b>Site Name</b>	Amakhala 051
	<b>Date</b>	17/10/2010 - 08:16
	<b>Project</b>	
	<b>CaseNID</b>	109157
	<b>Coords</b>	-32.847629, 25.981056

Page No: 1      **SiteAutoID:** 36156

**AlternateCode:**  
500 F259/2

Site Category: Building

**SiteComments:**

Farmhouse, maybe 1910 or so. Looks original with no modern additions. Lots of early fittings inside, wooden floors throughout except small entrance foyer on north end. Interior woodwork mostly very good. Windows and shutters in poor condition. Definite Grade 2 building. Outbuilding, stone and yellow-painted corrugated iron. 2nd small corrugated iron shed as well.

Damage Types: