Archaeological Site Report		SiteNo	9/2/003/0023
		<b>Site Name</b>	58 Beaufort Street, Grahamstown
		Date	
		Project	
		CaseNID	
Page No: 1	SiteAutoID: 37	Coords	-33.313925, 26.528014

BroadAgeCategory: LSA Site Category: Building

## **SiteComments:**

Archive Import History: Visual Description: DOUBLE STOREY, DOUBLE PILE 4 BAY ASYMMETRICAL PLAN. DOUBLE STOREY PART BRICK, PART WOODEN VERANDAH. CORRUGATED IRON ROOF. BRICK PLASTERED WALLS AND STONE PLINTH. ORIGINAL? DOOR AND SMALL PANE SASH WINDOWS. Colours: Site Features: Condition: Good Construction Date: Materials: Catalogue: Radford 1989 (b), No: S.21, Significance Category:

## AdminComments:

ON 1863 MAP. ON 1867 PHOTO SANS VERANDAH. THIS BUILDING C1850? SEE N.M.C. FILES. Bibliography archive:

Damage Types:

