

<b>Archaeological Site Report</b>	<b>SiteNo</b>	9/2/078/0012-013
	<b>Site Name</b>	19 Loop Street, Richmond
	<b>Date</b>	
	<b>Project</b>	
	<b>CaseNID</b>	
	<b>Coords</b>	-31.413419, 23.941049

Page No: 1      **SiteAutoID:** 27817

Site Category: Building

**Directions:**

Medium

**SiteComments:**

Archive Import History: Visual Description: Hall, long 3 bay on street. Corrugated iron saddle roof. Covered end gable with finial, barge boardi Colours: Site Features: Condition: Good Construction Date: Materials: Plastered brick : Corrugated iron Catalogue: Rudner, 1992, No: 010, Significance Category:

Damage Types: