Appendix B: SITE PHOTOGRAPHS



Photo 1. Herd of Merino Sheep grazing.



Photo 2. Signage at landowner's entrance gate.

MEMBERS: J.A. Bowers (M Tech, Pr.Sci.Nat.) & S.D. MacGregor (M.Sc., Pr.Sci.Nat.) Reg: 2006/023163/23



Photo 3. Existing 132kV ESKOM distribution line.



Photo 4. View facing Southwest of the wetland area near Borehole No.5 (30°49'33.98"S & 24°21'58.85"E).

MEMBERS: J.A. Bowers (M Tech, Pr.Sci.Nat.) & S.D. MacGregor (M.Sc., Pr.Sci.Nat.) Reg: 2006/023163/23



Photo 5. View facing West-southwest of an artificial pan located near Borehole No.4 (30° 49' 47.1" S & 24° 20' 49.9" E).



Photo 6. View facing East-northeast of a pan located at Borehole No.5 (30°49'31.01"S & 24°22'5.26"E).

MEMBERS: J.A. Bowers (M Tech, Pr.Sci.Nat.) & S.D. MacGregor (M.Sc., Pr.Sci.Nat.) Reg: 2006/023163/23



Photo 7. View facing southwest from the top edge of the ridge near Corner C.



Photo 8. View facing northwest of the grassland (or wetland) below the ridge near Corner C.

MEMBERS: J.A. Bowers (M Tech, Pr.Sci.Nat.) & S.D. MacGregor (M.Sc., Pr.Sci.Nat.) Reg: 2006/023163/23

EIA Report: The development of a 400 MW Solar Photovoltaic (PV) facility and associated infrastructure (Phase 3) on the Remainder of Farm Goede Hoop 26C, Portion 3 of Farm Goede Hoop 26C and other properties, Northern Cape Province



Photo 9. View facing southwest from the centre of watercourse Road Crossing No.2 in the middle of the study area.