

## Appendix C Site Photographs

The site photographs attached in this appendix were taken by the EAP during a site inspection in January 2022.

Please also refer to the various photographic plates in the specialist reports attached in Annexures E1 to E5 for additional photographic records of features relevant to the specific specialist discipline.

Figure 1: Typical vegetation on site consisting of grassland with scattered woody species .....	1
Figure 2: Scattered woody species amongst the Grassland .....	2
Figure 3: Livestock within the study site.....	2
Figure 4: Existing tracks on site.....	3
Figure 5: Existing Water Reservoir on site .....	3
Figure 6: Main Access Track from the R503.....	4
Figure 7: Livestock water trough within the study site.....	4
Figure 8: Existing access point from the R503 .....	5
Figure 9: Main Farm Access Gate.....	5
Figure 10: R503 running adjacent to the site.....	6
Figure 11: Site notice on the Boundary of the Site along the R503 .....	6
Figure 12: Existing powerlines traversing the property .....	7



*Figure 1: Typical vegetation on site consisting of grassland with scattered woody species*



*Figure 2: Scattered woody species amongst the Grassland*



*Figure 3: Livestock within the study site*



*Figure 4: Existing tracks on site*



*Figure 5: Existing Water Reservoir on site*



*Figure 6: Main Access Track from the R503*



*Figure 7: Livestock water trough within the study site*



*Figure 8: Existing access point from the R503*



*Figure 9: Main Farm Access Gate*



*Figure 10: R503 running adjacent to the site*



*Figure 11: Site notice on the Boundary of the Site along the R503*



*Figure 12: Existing powerlines traversing the property*