

### **2011-01-18 DPW VILLAGE REGENERATION HOUSES 83,84,85,86**

This set of houses are typical mid 1970's functional. Their exteriors don't really cause much excitement except that each has a different exterior appearance that distinguishes them from each other. This may be from later changes or by design but I have not been able to research or analyse this. Asbestos roof, gutters, watertanks, fascia.

The front doors are all meranti and in place with typical stained glass decorative circles. The stoeps all have a greenish tinted masonry tile.

The vibracrete perimeter walls are from more or less the same era and each also shows individualisation.

The interiors are more significant because the original meranti pelmets, typical 70's light fittings and parquet red teak floors have not been disturbed.



HOUSE 83 SOUTH FACE



HOUSE 83  
NORTH FACE  
AND STREET-  
SCAPE



HOUSE 84  
EAST FACE



HOUSE 84  
NORTH FACE



HOUSE 85  
FRONT  
ENTRANCE



HOUSE 85 NE

CORNER



HOUSE 85 EAST  
FACE



HOUSE 86  
NORTH FACE



HOUSE 86 NE  
FACE



HOUSE 86  
NW FACE



LIGHT  
FITTINGS



FRONT  
DOOR AND  
VERANDAH  
TILES



PELMET



PARQUET  
FLOORING