



East elevation to Problem Mkhize Road.



North elevation.



West elevation.




West elevation.






More recent outbuildings.



Original window.





Enclosed front veranda.



Edwardian fireplace which should be recycled.