

PHOTOS TAKEN AROUND THE PROPOSED LANDFILL SITE



Photo 1: The proposed landfill site will be located in undisturbed open veld as shown above



Photo 2: The above photo is showing the North-Easterly direction of the site



Photo 3: The above photo is showing the Easterly direction of the site. It shows the overview of Site 9 which has Eskom power lines running above it.



Photo 4: The above photo is showing the North-Easterly direction of Site 8 with a lot of loose shale rock.



Photo 5: Although the sites are clear in terms of shrubs and tree however there were some Aloe identified within the vicinity of the sites.



Photo 6: Due to the lack of a proper landfill site there is sporadic illegal dumping within and around Umzimkhulu as shown above.