

APPENDIX B:

Photographic Report



Photographic Report

A site visit was undertaken on 29 October 2022 to determine the environmental condition of the site.

The following photographs gives a representation of the conditions observed at the site.

Table of Figures:

Figure 1 Irrigation channel of the Vaal-Harts Irrigation Scheme at the southern border of the site..... 4

Figure 2 Infrastructure on the site..... 4

Figure 3 Indigenous and alien vegetation on the site..... 5

Figure 4 Camel Thorn trees on the site 5

Figure 5 Borehole on the site 6

Figure 6 Construction waste/disturbance on the site 6

Figure 7 Disturbance on the site: construction waste, old infrastructure, no ground cover 7

Figure 8 Invasive species on the site..... 7

Figure 9 Borehole on the site 8



Figure 1 Irrigation channel of the Vaal-Harts Irrigation Scheme at the southern border of the site.



Figure 2 Infrastructure on the site.



Figure 3 Indigenous and alien vegetation on the site



Figure 4 Camel Thorn trees on the site



Figure 5 Borehole on the site



Figure 6 Construction waste/disturbance on the site



Figure 7 Disturbance on the site: construction waste, old infrastructure, no ground cover



Figure 8 Invasive species on the site



Figure 9 Borehole on the site