

Photographs of the **Existing Affected Building and the New** 

Project:

**Liquid Storage Area on** Existing ERF 730, at 1474 South Coast Road, Mobeni

Client:


Metboard

(Properties Limited)



# **ANNEXURE C:**

Photographs of the Existing Affected Building:



## **AERIAL IMAGE OF THE SITE**

Proposed New Building

C6

Photograph number

Direction Photograph was taken.



### Photo: C1:

#### **North East View:**

Existing building 7.

Painted roof sheeting, with matching roof cladding.

Plaster & painted walls.

Position of the proposed new building.



#### Photo: C2:

#### **North East View:**

Existing building 7.

Painted roof sheeting, with matching roof cladding at clerestory level.

Plaster & painted walls.

Position of the proposed new building.



#### Photo: C3:

#### **North East View:**

Existing building 7.

Painted roof sheeting, with matching roof cladding.


Existing store room.

Plaster & painted walls.

Position of the proposed new building.

Existing passage access route.





### Photo: C4:

#### **Eastern View:**

Existing building 7.

Painted roof sheeting, with matching roof cladding. Saw-tooth roof profile.

Plaster & painted walls.

Existing Pharmaceutical factory. Existing building 4.



#### Photo: C5:

#### **North Western View:**

Existing building 7.

High level, industrial type steel framed windows.

Building 7.

Existing Pharmaceutical factory.

Existing service driveway.



## Photo: C6:

#### **Northern View:**

Existing building 7.

Roof cover between buildings 7 & 9.

High level, industrial type steel framed windows.

 $034\_08\_Annexure~C:~Photographs~of~the~existing~affected~building~-~1474~South~Coast~Road,~Mobeni:$ 



## Photo: C7:

#### **Western View:**

Existing building 7.

Saw-tooth roof profile.

Plaster & painted walls.

Steel framed windows have been removed.



## Photo: C8:

#### **Sothern View:**

Existing building 7.

Saw-tooth roof profile.

Steel framed windows have been removed.

Plaster & painted walls.



## Photo: C9:

#### **South Western View:**

Existing building 7.

Existing building 4.

Existing building 7.

Position for the new building.

Existing service driveway.