

SHAKAVILLE LANDFILL

Site photos taken on the 20th September 2017 and 18th October 2017



Figure 1: View towards the south east site showing the gravel road providing access to the site entrance form Mbozambo Street



Figure 2: View towards the site gate



Figure 3: View towards the north east showing the site entrance and the tap (red arrow)



Figure 4: Waste body on the north-eastern section of the site close to the gate and within the riparian area of a tributary of the Mbozamo River



Figure 5: Main access road within the landfill boundaries



Figure 6: Pigsty noted within the landfill boundaries

Examples of informal housing structures



Figure 7: Informal Housing structures on site

Other Infrastructure on site



Figure 8: Monitoring borehole protected by a manhole



Figure 9: Capped manhole without additional protection



Figure 10: Sewerline traversing the site and crossing a tributary of the Mbozamo River

Examples of small pockets of waste disposal noted on site



Figure 11: An example of one of the pockets of waste disposal



Figure 12: Empty syringe packaging

Examples of some plants growing on site



