

UMZIMKHULU LANDFILL

Site photos taken on the 21st September 2017 unless otherwise indicated



Figure 1: View towards the west showing the location of the landfill in relation to the P601 and the rolling hills (20 October 2017)



Figure 2: View towards the west showing the entrance to the site in relation to the P601 road to Franklin



Figure 3: Site entrance with the guardhouse in the foreground



Figure 4: Site toilet in the foreground and the guardhouse in the background



Figure 5: View towards the south east showing the site entrance (red circle)



Figure 6: View towards the south showing the compacted waste in the foreground and the fence and the P601 in the background



Figure 7: View towards the north west showing the waste on site showing uncompacted waste on the left and compacted waste on the right



Figure 8: Waste capping efforts



Figure 9: Examples of recyclables reclaimed from the landfill. Note the large bag filled with plastic bottles in the foreground and the cardboard boxes in the background

Waste streams of interest noted on site



Figure 10: Empty tablet containers



Figure 11: Insulin Syringes



Figure 12: Ink container spilling excess ink on the ground

Photographs from immediately outside the landfill boundaries



Figure 13: Goats feeding on plants immediately outside the landfill entrance



Figure 14: View towards the north west showing windblown litter in the foreground and the waste body in the background



Figure 15: Close up of the waste body viewed from the northern boundaries of the landfill. Note the poor state of the fence



Figure 16: Slanted fence due to the weight of the waste body pushing against shrubs to the fence



Figure 17: View towards the east towards showing the landfill in the foreground, Mankofu Village in the middle (red arrow) and uMzimkhulu CBD in the background (blue arrow)