

APPENDIX B

PHOTOGRAPHS



Plate B1: Photographs from the centre of the site looking North.



Plate B2: Photographs from the centre of the site looking North-West.



Plate B3: Photographs from the centre of the site looking West.



Plate B4: Photographs from the centre of the site looking South-West.



Plate B5: Photographs from the centre of the site looking South.



Plate B7: Photographs from the centre of the site looking South-East.



Plate B8: Photographs from the centre of the site looking East.



Plate B9: Photographs from the centre of the site looking North-East.




Plate B10: Photographs from the inside of the ATNS property on site.



Plate B11: Photographs from the inside of the ATNS property on site.



Plate B12: Drainage ditch near the walkway on Jones Road. Water pools and drains from here to the municipal stormwater drain.



Plate B13: The municipal stormwater drain located in the North-Western corner of the study area. It is located immediately adjacent to the pedestrian walkway.



Plate B14: Manicured gardens located towards the southern end of the site. During the site visit garden staff were busy maintaining the gardens. Lawn mowing occurs regularly.



Plate B15: Pedestrian walkway and stormwater mains showing along Jones Road, toward the North-Western corner of the study area.



Plate B16: View of the site from Jones Road pedestrian walkway



Plate B16: View of the site from Jones Road pedestrian walkway.



Plate B16: View of the Jones Road pedestrian walkway.



Plate B16: Invasive Gum trees on site..



Plate B17: Drainage ditch outside fuel storage tank facility, on the south end of site.



Plate B18: Vegetation cover inside the ATNS portion of the site.



Plate B19: ATNS communications tower on site.



Plate B20: Electrical switching facility on the ATNS portion of site.



Plate B21: Invasive pine trees on site.



Plate B22: Looking across the ATNS part to site (near white bakkie in background).



Plate B23: General view of site.