


APPENDIX B: PHOTOGRAPHS



Greenbushes Erf 77
33°55'18.56"S; 25°25'32.40"E



PHOTO SITE A: SOUTH-EASTERN SECTION OF THE SITE



Natural groundcover observed within certain sections of the property.



Illegal dumping observed along the inner boundary of the property.

PHOTO SITE B: NORTH-WESTERN SECTION OF THE SITE



Alien vegetation and some spoil material covered with grass.



View of the site from the north-west corner.

PHOTOS OF NEARBY SURFACE WATER FEATURES



Drainage line located approximately 80m from the south-east corner of the site.



Wetland located on neighbouring property approximately 90m east of the site.