

BRIDGE NB35 ON R27 SECTION 8 AT KM 22.7



Figure B1: Bridge NB35: View of the R27 across the bridge deck (facing south-east)(Photo provided by Aurecon)



Figure B2: Bridge NB35: View of vegetation in the riverbed downstream of the bridge (facing south-east)(Photo provided by Aurecon)



Figure B3: Bridge NB35: View to the downstream of the bridge (facing west)(Photo provided by Aurecon)



Figure B4: Bridge NB35: View of vegetation in the riverbed upstream of the bridge (facing east)(Photo provided by Aurecon)



Figure B5: Bridge NB35: View to the upstream of the bridge (facing east)(Photo provided by Aurecon)

BRIDGE NB36 ON R27 SECTION 8 AT KM 34.9



Figure B.6: Bridge NB36: View of the R27 across the bridge deck (facing east)



Figure B7: Bridge NB36: View of the bridge from within the watercourse (facing south)



Figure B8: Bridge NB36: View to the downstream of the bridge (facing north-west)



Figure B9: Bridge NB36: View of vegetation upstream of the bridge (facing south)

BRIDGE NB37 ON R27 SECTION 8 AT KM 59.2



Figure B10: Bridge NB37: View of the R27 across the bridge (facing east)



Figure B11: Bridge NB37: View of vegetation in the riverbed downstream of the bridge (facing north-west)



Figure B12: Bridge NB37: View to the downstream of the bridge (facing south-west)



Figure B13: Bridge NB37: View of vegetation in the riverbed upstream of the bridge (facing west)



Figure B14: Bridge NB37: View to the upstream of the bridge (facing north)

BRIDGE NB38 ON R27 SECTION 8 AT KM 67.1



Figure B15: Bridge NB38: View of the R27 across the bridge with the outskirts of Calvinia in the background (facing north)



Figure B16: Bridge NB38: View of the bridge from within the watercourse (facing west)(photo provided by Aurecon)



Figure B17: Bridge NB38: View of vegetation in the riverbed downstream of the bridge (facing north-east)



Figure B18: Bridge NB38: View to the downstream of the bridge (facing south-west)



Figure B19: Bridge NB38: View of vegetation in the riverbed upstream of the bridge (facing south-west)(photo provided by T Hart)



Figure B20: Bridge NB38: View to the upstream of the bridge (facing east)

BORROWPIT BP R27-8 KM 32.6 RHS 6.2



Figure B21: BP R27-8 KM 32.6 RHS 6.2: View of the site, with the abandoned Iceland Spar mine outlined in yellow (facing south-east)(photo provided by Dr D MacDonald)



Figure B22: BP R27-8 KM 32.6 RHS 6.2: View of the existing tailings heap to be excavated (facing south-west)



Figure B23: BP R27-8 KM 32.6 RHS 6.2: View of the surrounding area (facing west)

BORROWPIT BP R27-8 KM 45.0 RHS 0.2



Figure B24: BP R27-8 KM 45.0 RHS 0.2: View from the R27 towards the existing excavated area (facing south-west)



Figure B25: BP R27-8 KM 45.0 RHS 0.2: View towards the R27 (facing north-east)



Figure B26: BP R27-8 KM 45.0 RHS 0.2: View of existing disturbed areas (facing north)

BORROWPIT BP R27-8 KM 61.60 RHS 1.0



**Figure B27: BP R27-8 KM 61.6 RHS 1.0: View of existing disturbed area (facing south-east)
(photo provided by Dr D MacDonald)**



Figure B28: BP R27-8 KM 61.6 RHS 1.0: View of surrounding area (facing south-east) (photo provided by Dr D MacDonald)



Figure B29: BP R27-8 KM 61.6 RHS 1.0: View of eastern edge of the existing borrow area (facing south-east) (photo provided by Dr D MacDonald)