

## Photographs



Figure 1: General view of the vegetation characteristics of the site



Figure 2: Current infrastructure on site (Watershed SS main entrance)





**Figure 3: Existing powerlines within the study area**



**Figure 4: Existing infrastructure within the site**





Figure 5: View of the study area from the north-eastern corner of the site



Figure 6: Line of stones near substation fence (probably stone clearing)





Figure 7: View of the site towards the east of the substation



Figure 7: View of the site towards the east of north of the substation



Figure 9: View of the site towards the east of the north east of the substation



Figure 9: View of the site towards the east of the south of the substation