

**KWAGGAFONTEIN SITE PHOTOS**



**Figure 1:** View of the Kwaggafontein landfill site from the north west



**Figure 2:** Eskom distribution line along the landfill side and the R537



**Figure 3:** The R357 (Moloto Road) running along the north west of the site



**Figure 4:** Ablution facilities are observed on the eastern boundary of the site



**Figure 5:** A cemetery is observed on the western boundary of the site



**Figure 6:** Municipal servitudes are observed along the south western boundary of the site



**Figure 7:** Waste/Litter is seen at the south western boundary of the site



**Figure 8:** Waste/Litter is seen at the south eastern boundary of the site



**Figure 9:** View of the landfill site from the eastern boundary of the site



**Figure 10:** A degraded buy back centre is observed on the western boundary of the site



**Figure 11:** Reclaimers are observed collecting and sorting waste material within the landfill site.



**Figure 12:** View of the Kwaggafontein landfill site from the south of the site