JAN KEMPDORP INFILL DEVELOPMENT

PHOTOGRAPHIC HISTORY



Photo 1: North-eastern view of the proposed side showing the vegetation condition



Photo 2: South-eastern view of the proposed site

JAN KEMPDORP INFILL DEVELOPMENT



Photo 3: Typical vegetation on the Proposed Site



Photo 4: View of the overhead powerline

JAN KEMPDORP INFILL DEVELOPMENT



Photo 5: South-western View of the proposed site