

## APPENDIX C: PHOTOGRAPHS: MBAZWANA WASTE FACILITY



Google Earth satellite image of the Mbazwana Waste Facility and its site elements

Picture	Description
 <p>2015-09-02</p>	<p>Looking north-west.</p> <p>Guardhouse at site entrance. There is a guard controlling access.</p>
 <p>2015-09-02</p>	<p>Looking north-east.</p> <p>Signage at site entrance.</p>



Looking north-west.  
Contested access road  
and dump site.  
Photograph taken near  
Position 4.



Looking north.  
Litter strewn around site.  
Photograph taken near  
Position 1.



Looking west.  
Litter strewn around the  
original dump area.  
Photograph taken near  
Position 1.



Looking north-west.  
Note the track that leads  
to the new dumping area  
at Position 3.  
Photograph taken near  
Position 1.



Looking south.

JoJo water storage tanks,  
possibly a borehole.

Photograph taken near  
Position 4.



Looking north-west.

Track leading to the new  
dumping area at Position  
3.  
Note the sandy ground  
conditions.

Photograph taken near  
Position 1.



Looking south-west.

Glass stockpile.

Photograph taken near  
Position 1.



Looking north-north-west.

Stockpiled recyclables  
along the track.

Photograph taken near  
Position 2.



Looking south.  
Building waste alongside the track.  
Photograph taken near Position 2.



Looking west.  
Bags of garden waste along the track.  
Photograph taken near Position 2.



Looking south-west.  
General unsorted waste that has been tipped by a municipal truck.  
Photograph taken near Position 3.



Looking west-south-west.  
General unsorted waste that has been tipped by a municipal truck.  
Photograph taken near Position 3.



Looking north-west.

General waste being sorted by EPWP workers.

Photograph taken near Position 3.



Looking east.

The track that leads back to the original dumping area.

Photograph taken near Position 3.