


Appendix C: Site Photographs



Appendix C: Site Photographs

A



B



C



Photo A: Disused railway line.

Photo B: Northern view of the study site from the centre.

Photo C: North north eastern view of the study site from the centre.

Appendix C: Site Photographs



Photo D: Eastern view of the study site with the existing Eskom servitude crossing the property.

Photo E: East south east view of the property with existing access road.

Photo F: Southern view of the study site.

Appendix C: Site Photographs



Photo G: South south western view showing the transmission lines running south west to Kronos substation.

Photo H: Western view of the study site.

Photo I: West north west view of the study showing Eskom servitude with existing transmission lines.

Appendix C: Site Photographs




Photo J: Transmission lines running south east to Kronos substation.

Photo K: Kronos substation in the distance . Note transmission lines along the gravel road.

Photo L: Fence and transmission lines running along the gravel road to Kronos.

Photo M: Fence and transmission lines coming from the north.