


FLOOR FINISH	• ex. quarry floor tile to be pressure cleaned and sealed as per spec. - 115.44m ²
WALL FINISH	• Existing red satin face brick 1.4m above f.f.l to be pressure washed , mortar joints to be filled were required and sealed as per specifications Existing plaster & paint above red satin face brick - Walls to be scraped, treated, fill all imperfections. - Walls to receive new finish as per specifications
CEILING	• - scrape off existing flaking paint , treat and fill all imperfections to receive new finish as per spec.

ROOM NO. SOUTH WING CORRIDOR FIRST FLOOR	ROOM NAME - PROJECT: NATAL COMMAND -DILAPIDATION REPORT	SCALE: 1/50	DRWG.No: 21126
 P.O.BOX 37188 OVERPORT DURBAN 4067 TELE : 2097245/6 FAX : 2097247 E-MAIL :seedat@ion.co.za AHMED.SEEDAT-ARCHITECT REG no :3140(S.A.C.A.P)	DRAWING TITLE: ROOM AND OFFICE DATA SHEETS	DATE: DEC 2022	PAGE.No: 1