

- Walls to be scraped, treated, fill all imperfections.

le to receive new finich as ner creatifications

	- Walls to receive new finish as per specifications				
	Timber Wall Paneling: 1.4m high				
	- All timber panels to be inspected for wood rot and water damage.				
	- Affected panel to be removed & replaced with solid timber veneered paneling to match.				
	- All paneling to be sanded, sealed, stained to matched existing				
CEILING •	NG • - scrape off existing flaking paint , treat and fill all imperfections to receive new finish as per spec.				
DOOR •	door frames to be repaired with salvaged and made good to match ex.				
	Doors: Refer to door detail				
ROOM NO. NORTH WING FOYER ROOM		ROOM NAME -			
<i>5</i> 8 0	P.O.BOX 37188	PROJECT:	SCALE:	DRWG.No:	
OPI OFF	OVERPORT	NATAL COMMAND -DILAPIDATION REPORT	1/50	21126	
	DURBAN 4067		1/00	21120	
	TELE : 2097245/6				
P P S S S S S S S S S S S S S S S S S S	FAX : 2097247	DRAWING TITLE:	DATE:	PAGE.No:	
	E-MAIL :seedat@ion.co.za	ROOM AND OFFICE DATA SHEETS	DEC 2022		
1 1 7 5	AHMED.SEEDAT-ARCHITECT			1	
	REG no :3140(S.A.C.A.P)			·	