<u>Key features observed during the site inspection conducted on October 2022 for the proposed Lengana Solar Power Plant, near Excelsior, Free State province:</u>



Plate 1: The site (taken towards the north)



Plate 2: The site (taken towards the north east)










Plate 5: The site (taken towards the south).







Plate 6: The site (taken towards the south west).

Plate 7: The site (taken towards the west).

Lengana Solar Power Plant (RF) (Pty) Ltd.



Plate 8: The site (taken towards the north west).

Lengana Solar Power Plant (RF) (Pty) Ltd.



Plate 9: Significant portions of remaining natural grassland are dominated by a dense grass layer and though it only has a moderate diversity, is still in a relatively good condition.





Lengana Solar Power Plant (RF) (Pty) Ltd.

Plate 10: The low sandstone hill clearly differs from the surrounding habitats and will likely contain elements of high conservation value

