



DAMAGED ROOF



DRIVEWAY



EAST ELEVATION AND FRONT GARDEN



EAST ELEVATION



EXISTIG ENTRANCE STAIRS



EXISTING BACK VERANDA





EXISTING BEDROOM WITH INTERLEADING DOOR



EXISTING BATHROOM




EXISTING DOOR



EXISTING ENTRANCE DOOR




EXISTING BEDROOM



EXISTING PANTRY



EXISTING STUDY



EXISTING HALLWAY LOOKING AWAY FROM MAIN ENTRANCE



EXISTING HALLWAY LEADING TO FRONT DOOR



FRONT VERANDA (2)



FRONT VERANDA (3)





FRONT GARDEN AND BOUNDARY WALL



FRONT VERANDA



GATE ENTRANCE EXISTING BACK VERANDA



INNES ROAD LOOKING NORTH EAST



INNES ROAD LOOKING SOUTH WEST (2)



INNES ROAD LOOKING SOUTH WEST





MAIN ENTRANCE (2)



MAIN ENTRANCE



SIDE VERANDA



EXISTING KITCHEN



EXISTING LIVING ROOM



SOUTH EAST ELEVATION



SOUTH ELEVATION



VIEW FROM PROPERTY



WEST ELEVATION