

SWA515624485 - DR JS MOROKA MUNICIPALITY



Figure 1: Picture showing existing electricity in the study area



Figure 2: Picture showing pole where the powerline will be supplied from



Figure 3: Picture showing the existing vegetation



Figure 4: Picture showing existing road and fence boundary infrastructure



Figure 5: Picture showing pole position of the powerline



Figure 6: Picture showing one of the protected species



Figure 7: Another picture showing another pole position



Figure 8: Another picture showing Acacia tree that is affected by the powerline