



Photo 1: East-facing side of cottage looking towards internal circle road



Photo 2: North-facing side of cottage, with indigenous bush along northern boundary



Photo 3: River view from cottage deck towards the west



Photo 4: West facing side of cottage, with slope and embankment between cottage and boat house



Photo 5: View of cottage from SW, showing southern boundary of stand



Photo 6: Westerly view towards river, with cleared bush along southern boundary

**PLATE 1 :
PHOTOGRAPHIC VIEW OF THE SITE**

**No 46 Rivertide Shareblock,
Kromme River, Eastern Cape**



Photo 7: Proposed site for new house, between cottage and boat house



Photo 8: Proposed site for new house and driveway, between cottage and boat house



Photo 9: Site for proposed activity slopes downward towards boat house and river



Photo 10: Vegetation on embankment to be cleared for proposed deck and house



Photo 11: Area along southern boundary to be utilised for extended deck and driveway



Photo 12: Existing deck to be extended to link cottage to proposed new house

**PLATE 1 :
PHOTOGRAPHIC VIEW OF THE SITE**

**No 46 Rivertide Shareblock,
Kromme River, Eastern Cape**



Photo 13: Corrugated iron cottage sunken in, and resting on wooden framework



Photo 14: Two rainwater tanks and the conservancy tank on north-facing side of cottage



Photo 15: Indigenous bush serves as screen between property and neighbour



Photo 16: Downstream view from boat house, showing high-water mark



Photo 17: Upstream view from boat house, with shareholders' jetties



Photo 18: View from SE corner of stand, showing pole for telephone and power lines

**PLATE 1 :
PHOTOGRAPHIC VIEW OF THE SITE
No 46 Rivertide Shareblock,
Kromme River, Eastern Cape**