













Photo 1 – Existing River Crossing Along Ingonyama Road







Existing Powerlines, lighting control box and transformer adjacent to the proposed road



Signs of Pollution and Erosion









Small businesses adjacent to the proposed road















East of the proposed route towards the river crossing