

The proposed upgrade of Storm Water and Environmental Systems in the Port of Saldanha site photographic report.



Four points photos - Western side of the port at ponds (Pond 1, 2 and 3) to be upgraded.

Four points photos - Northern side of the port at ponds (Pond 1, 2 and 3) to be upgraded.



Four points photos - Eastern side of the port at ponds (Pond 1, 2 and 3) to be upgraded.

Four points photos – Southern side of the port at ponds (Pond 1, 2 and 3) to be upgraded.



Pond (pond 3) that need to be upgraded.

Pond (Pond 2 and 3) that need to be upgraded.



Pond (pond 4) that need to be upgraded.

Water that need to be channeled in the ponds ponding on the road.



Reeds in the pond that need to be removed.



Weeds and alien plants that need to be removed.



Sludge in the ponds that need to be removed.



Sludge that is channeled to the natural environment.



Sludge in the water channel.



Sludge (contaminated water with iron ore) fill water channel.