



APPENDIX B

SITE PHOTOGRAPHS: HARTSWATER WASTE DISPOSAL FACILITY

Picture	Description
	<p>Access road to the landfill, with the landfill to the right and a Semi-formal residential area to the left</p>
	<p>Fence surrounding the landfill on the southern side.</p> <p>Indication of wind-blown litter</p>



Evidence where the fence on the south-eastern side is cut.

Illegal dumping and littering.



Wetland in the centre of the landfill



Wetland in the centre of the landfill



Illegal dumping within the landfill boundaries



Evidence of the wetland to the left, previous quarrying and erosion to the right.



Semi-formal housing within the landfill boundary, on the eastern side.



Current status of the landfill to the south-western side.



Illegal littering and burning of waste



Semi-formal housing within the existing perimeter of the landfill



Illegal dumping within the landfill perimeter.