

**APPENDIX B**

**SITE PHOTOGRAPHS: JAN KEMPDORP WASTE DISPOSAL FACILITY**

Picture	Description
 <p>A photograph showing an access gate and fence of an existing landfill. The area is heavily littered with various types of waste, including plastic bags, cardboard boxes, and other debris. A brick building is visible in the background. The date '17.08.2015' is printed in orange in the bottom right corner of the image.</p>	<p>Access gate and fence of the existing landfill, indicating no access control to be conducted.</p> <p>Littering and illegal dumping taking place outside the existing boundaries of the landfill.</p>
 <p>A wide-angle photograph showing a general view of the landfill. The ground is covered with a vast amount of unsorted waste, including plastic, paper, and other debris. There is no visible covering or compaction of the waste. The date '17.08.2015' is printed in orange in the bottom right corner of the image.</p>	<p>General view of the landfill.</p> <p>No covering or compaction is being done.</p>



Access road leading to the landfill.

Littering and illegal dumping taking place outside the existing boundaries of the landfill.



Scavengers living within the footprint of the existing landfill



Evidence of littering outside of the landfill footprint.

Cemetery located to the east of the landfill



Littering and illegal dumping taking place outside the existing boundaries of the landfill.



Littering and illegal dumping taking place outside the existing boundaries of the landfill.



Water canal associated with the Vaal-harts irrigation scheme, located adjacent to the west of the landfill.