



Figure 1: Main entrance gate to Middelburg Dam



Figure 2: Sluice of the Dam south of the project area





Figure 3: View of the southern section of the project area



Figure 4: View of the far eastern section of the project area





Figure 5: View of the North Eastern section of the project area



Figure 6: Eastern part of the project area. Jungle gym is visible.





Figure 7: Southern section of the project area. A ablution block is visible on the right side of this image



Figure 8: One of the houses on the property





Figure 9: Pump Station in the north western corner of the study area



Figure 10: Area in the north easter section is used for dumping waste





Figure 11: View of the dam



Figure 12: View of a rocky outcrop east of the entrance gate