

**PROPOSED UPGRADING OF EXISTING MUNICIPAL SEWAGE TREATMENT PLANT AT SEKGOSESE
SECONDARY SCHOOL ON PART OF THE FARM ROERFONTEIN 161-LT, SENWAMOKGOPE, LIMPOPO
PROVINCE – SITE PHOTOS**



Entrance to the site.



Invasive *Lantana camara* onsite.



Indigenous vegetation outside the site.



Entry of raw sewage into the primary pond.



Inlet structure.



Primary pond 1.



Secondary pond 1.



Secondary pond 2.



Tertiary pond 1.



Tertiary pond 2.



Tertiary pond 3. Bulrushes growing in the pond are aiding in bio-remediation (natural treatment).