

## Appendix 3: Photographs



**Photograph 1:** Component 1 - Concrete Pole Fence around Core Area under construction.



**Photograph 2:** Component 1 - Previous fence needs to be disposed of appropriately.



**Photograph 3:** Component 2 - The ablation facility at the Blue Pools picnic site is under construction.



**Photograph 4:** Component 3 - The ablation facility at Thomeng Falls is under construction.



**Photograph 5:** Component 4 - Road to Thomeng is under construction.



**Photograph 6:** Component 5 - Mine Workers Compound is to be restored.



**Photograph 7:** Component 6 - Mine Manager's Office to be restored.



**Photograph 8:** Component 7 - Power House to be restored.



**Photograph 9:** Component 8 - The improvement of the proposed entrance area and parking area can be done so as to screen parking



**Photograph 10:** Component 9a - Hrdlička's, a sensitive heritage site requiring conservation



**Photograph 11:** Component 9b - Equus Cave, a sensitive heritage site requiring conservation measures.



**Photograph 12:** Component 9c - Black Earth Cave, a sensitive heritage site requiring conservation measures.



**Photograph 13:** Component 9d - Oxland Large Mammal Fossil Site, a sensitive heritage site requiring conservation measures.



**Photograph 14:** Component 10 - Signage along existing trails.



**Photograph 15:** Component 11 - Memorial site and proposed pavilion site.



**Photograph 16:** Component 13 - Historic building in Buffer Zone.



**Photograph 17:** Component 14 - Lime Kiln Area.



**Photograph 18:** Component 14 - Lime Kiln Area.