

Appendix 3: Photographs of the Study Area

Site Photographs of the Existing Ship Repair Facility at the Port of Mossel Bay



Figure 1: Entry into the Port of Mossel Bay



Figure 2: View of the wooden lead-in jetties



Figure 3: A ship on the existing wooden cradle



Figure 4: Close-up view of the existing wooden cradle



Figure 5: Existing slipway



Figure 6: Existing winch house



Figure 7: Operations building



Figure 8: Vessel on the slip for hull inspection and new corrosion protection application



Figure 9: Existing lead-in jetties