

**A view from the shore line from the Kromme Estuary to the east, of the existing boat house and dwelling in the background.**

**Both structures are of timber and corrugated iron construction with fibre cement roof covering. The insert to the right is another view from the estuary to the north.**







**A view from the front boundary of the site to the south west, of the existing dwelling. This structure is constructed mainly of timber and corrugated iron walling with fibre cement roof covering. The insert to the left is a view from the south west.**







**A view of the cleared areas along both the side boundaries of site 46 which provides a clear visual of the ground in these areas.**





**A view to the south down stream of the Kromme estuary showing the shoreline.**

**The Kromme estuary is approximately 4.8km to the sea from this point. The insert to the right is up the Kromme estuary which is approximately 9.3 km to the end of the tidal estuary and the beginning of the fresh water entry point of the Kromme River.**







**Left: A pit 500mm square excavated in the middle of the site showing the composition of the topsoil overburden – note the brown siltstone flakes. This hole was possibly dug to remove a root stock of a bush that was removed.**



**Left: a trench excavated around the base of the existing dwelling on site.**





**A view from the front boundary of site 46 towards the Kromme estuary – the existing dwelling is to the right and the boat house right/centre. The bush on the left has been cleared. The insert bottom/left is an area investigated for any visible heritage resources.**





**Left: The piece of pottery found adjacent to the existing dwelling showing sailboat ship mark of Grindley pottery made in England. Bottom : a panoramic view of site 46 from the front deck of the existing dwelling to the south west.**

