

## APPENDIX B- Site photographs



Photo1: View of the site along the Shoprite Hyper



Photo 2: View of site along the Shoprite fence



Photo 3: Existing Developments on site



Photo 4: Existing overhead powerlines on site



Photo 5: Existing 300mm Asbestos Pipeline



Photo 6: View of the crossing for Hyperama