#### Boiler

Merchant ships were typically fitted with Scotch boilers, where the fire passes through tubes surrounded by water (Brown 1931: 167). The *Karin* carried water for her boiler in the aft peak tank (Appendix A: 92).



- Key
  - Dome
  - Main stop valve
  - . Main steam pipe
  - Auxiliary steam valve Auxiliary steam pipe
  - Back-end plate
  - . Brine / scum valve
  - . Brine / scum pipe
- 9. Main check valve
- 10. Main feed pipe
- 11. Donkey check valve
- 12. Donkey feed pipe
- Communication cock
  Blow out cock
- 14. Blow out cock 15. Blow out pipe
- 16. Boiler shell
- 17. Stay nuts and washers

**Figure 143:** Diagram of the back end plate of a boiler (Paasch 1890: Plate 48)



**Figure 144:** The outer surface of the boiler's back end plate (Photo: Maitland)





**Figure 145:** Close-up of a boiler stay nut and gasket on the outer surface of the boiler's back end plate (Photo: Maitland)

**Figure 146:** Blow out or blow off cock (Paasch 1890: Plate 48; Photo: Maitland)



- 1. Dome 2. Crown of dome 3. Stop valve / Main stop valve 4. Main steam pipe 5. Auxiliary steam valve 6. Auxiliary steam pipe 7. Whistle pipe valve 8. Steam gauge cock 9. Steam gauge pipe Safety valves 10. 11. Water gauge column 12. Steam cock of 11 13. Water cock of 11 14. Test cocks 15. Water gauge glass 16. Drain pipe 17. Blow off cock 18. Blow off pipe 19. Boiler stays 20. Boiler stay nuts 21. Steam space 22. Water level 23. Brine pipe Dogs on crown of combustion chamber / fire 24. box 25. **Boiler** tubes 26. Fire box 27. Fire box stays 28. Fire bridge 29. Fire bars 30. Fire bars bearers 31. Furnace 32. Ash pit 33. Furnace front 34. Fire door 35. Baffle plate Dead plate 36. 37.
  - Front tube plate of boiler
  - Back tube plate of boiler
  - Back end plate of boiler
  - Back plate of fire box
  - Crown of fire box

38.





Fire box stays Boiler stays Figure 148: Inner surface of the boiler back plate (Photo: Maitland)



Figure 149: Close-up of the boiler stays on the inner surface of the boiler back plate (Photo: Maitland)

Karin Wreck Report / The Construction / Page 43



Figure 150: Diagram. Right side — Front tube plate of a boiler; Left side — Inside view of back end plate (Paasch 1890: Plate

#### Key:

- Dome
- Crown of dome
- 3. Steam gauge cock
- Steam gauge pipe 4.
  - Safety valve
- Waste steam pipe 6.
  - Auxiliary steam valve
  - Auxiliary steam pipe
- Front tube plate of boiler 10.
  - Outside nuts and washers of boiler stays
  - Boiler tubes
- Stay tubes 12.
- Hand hole 13.
- Sludge hole 14.
- 15. Furnace front
- Furnace door 16.
- Ash pit 17.
- 18. Back tube plate 19.
  - Back end plate of boiler inside view
  - Dogs, on crown of fire box
  - Fire bridge
- 22. Fire bars
- 23. Furnace crown
- 24. Fire box stays
- 25. **Boiler shell**



Figure 151: Possible front tube plate (Photo: Maitland)



Figure 152: Front tube plate of boiler (Photo: Maitland)



**Figure 153:** Boiler shell plate (Brown 1931: 167; Photo: Maitland)



Figure 154: Boiler shell plate (Photo: Maitland)



**Figure 155:** The iron lining of the ash pit and furnace (Brown 1931: 167; Photo: Maitland)



Figure 156: Furnace door (Brown 1931: 166; Photo: Maitland)



Figure 157: Possible fire bars (Photo: Maitland)



**Figure 158:** Brass boiler tube ends or buffer plate from the condenser (Renda 2010; Bauer 1905: 271;; Photo: Maitland)



**Figure 159:** Ash pit inspection door (Renda 2010; Photo: Maitland)



**Figure 160:** Pile of brass boiler pipes (Photo: Maitland)



**Figure 161:** Possibly the remains of safety valves (Photo: Maitland)



Figure 162: Brass pipes and flanges (Photo: Maitland)



**Figure 163:** Curved iron pipe and flange - there were numerous pipes leading to and from the boiler (Photo: Maitland)



Figure 164: Wider brass pipe from the boiler (Photo: Maitland)

Engine

The *Karin* had a triple expansion engine and the following specifications are listed as: horse power - normal; working pressure - 195; heating surface 1400 square feet; speed - 8/9 knots; consumption - 6 tons. The engine was built by Stork Bros. & Co., engineers. The engine was placed aft in the vessel (Appendix A: 3)



- 34. High pressure cylinder cover
- 35. Intermediate cylinder
- 36. Intermediate cylinder cover
- 37. Low pressure cylinder
- 38. Low pressure cylinder cover
- 39. High pressure valve casing/box/steam chest
- 40. Intermediate valve casing/box/steam chest
- 41. Low pressure valve casing/box/steam chest
- 42. High pressure balance cylinder
- 43. Intermediate balance cylinder

- Key:
  - Bed plate
  - Crank shaft
  - Main bearings
  - Cylinder columns
  - Hand rail
  - Reversing wheel
  - Weigh shaft
  - Weigh shaft levers
  - High pressure connecting rod
  - Intermediate connecting rod
  - Low pressure connecting rod
  - . Condenser
  - Condenser door
  - Circulating pump discharge pipe
  - Eduction pipe
  - High pressure eccentric gear
  - . Intermediate eccentric gear
  - Low pressure eccentric gear
  - High pressure valve spindle
  - High pressure valve spindle guide
  - . Intermediate valve spindle
  - . Intermediate valve spindle guide
  - Low pressure valve spindle
  - Low pressure valve spindle guide
    - High pressure piston rod
  - High pressure piston rod crosshead
  - Intermediate piston rod
  - Intermediate piston rod crosshead
  - Low pressure piston rod
  - Low pressure piston rod crosshead
  - . Pump levers
  - Pump links
  - High pressure cylinder
- 44. Low pressure balance cylinder
- 45. High pressure cylinder escape valve
- 46. Intermediate cylinder escape valve
- 47. Low pressure cylinder escape valve
- 48. Starting / auxiliary valve
- 49. Starting valve pipe
- 50. Auxiliary stop valves
- 51. Tail rod of high pressure piston
- 52. Tail rod of intermediate piston
- 53. Tail rod of low pressure piston
- 54. Stuffing boxes

Figure 165: Diagram of a triple expansion engine (Paasch 1890: Plate 50)





Main bearing Crank shaft Crank web Turning wheel

**Figure 166:** Section of a small crank shaft (Paasch 1890: Plate 59; Photo: Maitland)



Crank shaft

Thrust shaft

**Figure 168:** Crank shaft attached to the thrust shaft (Paasch 1890: Plate 59; Photo: Maitland)



**Figure 170:** Possibly part of the crank shaft where it connects to the propeller shaft, the flat edge on the flange indicates it rested on something flat (Photo: Maitland)

Figure 167: Side view of the small crank shaft (Photo: Maitland)



Figure 169: Side view of the crank shaft and its attachment to the thrust shaft (Photo: Maitland)



**Figure 171:** High / intermediate / low pressure connecting rod (Photo: Maitland)

Karin Wreck Report / The Construction / Page 48



Figure 172: Part of a connecting rod, note the stuffing box glands on either side (Photo: Maitland)



**Figure 173:** Part of a connecting rod, possibly from an eccentric gear (Photo: Maitland)



**Figures 174 - 175:** Two views of connecting rods from the triple expansion engine, the high level of concretion makes identification difficult (Photos: Maitland)



Piston Piston rod

Stuffing box

**Figures 176 - 177:** Views of the piston; in a triple expansion engine, there would have been three (Paasch 1890: Plate 51; Photo: Maitland)



**Figure 178:** Possible engine casing breather (Renda 2010; Photo: Maitland)



**Figure 179:** Possible cylinder head inspection cover (Renda 2010; Photo: Maitland)



**Figure 180:** Sea chest grating, this is fitted onto the hull and filters the incoming water (Renda 2010; Photo: Maitland)



Connecting flange Stuffing box gland **Figure 181:** Connecting flange with a stuffing box gland(Photo: Maitland)



**Figure 182:** Double stuffing box gland (Photo: Maitland)



**Figure 183:** Possible stop valve gear on the triple expansion engine (Photo: Maitland)



**Figure 184:** Three way cock, it has a connecting flange, the remains of the gasket are visible (Photo: Maitland)



Figure 185: Assortment of ball valves, throttle valves and stop cocks (Photo: Maitland)



**Figure 186:** Possible valve, there were numerous valves which regulated the flow of water, air or steam throughout the engine room (Paasch 1890: 143; Photo: Maitland)



Figure 187: Close-up of the manufacturer's stamp on the artefact -50 H. The valve appears to be brass (Photo: Maitland)



**Figure 188:** Double-seated valve (Bauer 1905: 141; Photo: Maitland)



**Figure 189:** Cooling water inlet valve (Renda 2010; Photo: Maitland)



Figure 190: Inner valve (Renda 2010;Photo: Maitland)



**Figure 191:** Inner and outer valve parts (Renda 2010; Photo: Maitland)



Figure 192: Assortment of flanges, gaskets and washers (Photo: Maitland)



**Figure 193:** Assortment of miscellaneous equipment (Carpenter 1917: 555; Photo: Maitland)



**Figure 194:** Spring still attached to a rod, probably part of a safety valve (Paasch 1890: Plate 52; Photo: Maitland)



Springs Ball valve Valve handle Stuffing box glands **Figure 195:** Assortment of miscellaneous equipment (Photo: Maitland)







Door handle Pipe joiner Gasket Handle Figure 197: Assortment of miscellaneous equipment (Photo: Maitland)



Figure 198: Intact gasket in gland (Photo: Maitland)



Figure 199: Close-up of gasket with the manufacturer's stamp — James Walker & Co. Carford St. West India Dock Rd. London (Photo: Maitland)



Figure 200: Globe valve, drip tap valve and stop cocks (Photo: Maitland)



Figure 201: The remains of a Bourbon steam pressure gauge (Morrison 1895:113; Photo: Maitland)

#### Condenser

Paasch (1890: 109) defines a condenser as follows, "a cast iron appatatus, into which steam after its use in the cylindars is discharged for condensation; i.e. : reduced to water. This water is taken by the air-pump and brought into the hotwell, and from thence by the feed-pump through the feed-pipe supplied to the boilers."



#### cy.

- Bed plate
- Cylinder columns
- Cylinder
- Cylinder cover
- Slide valve casing door
- Escape valve
- Stuffing box
- Piston rod
- Piston rod crosshead
- Guide blocks; guide shoes
- Crosshead guide
- . Connecting rod
- . Connecting rod bottom end bolt
- . Crank web; web of crank shaft
- Coupling flange
- 6. Main bearing
- Main bearing bolts
- B. Pump lever
- . Centre gudgeon
- D. Eduction pipe
- Circulating pump discharge pipe
- 2. Condenser door
- . Circulating pump
- . Bilge pump
- Bilge pump suction pipe
- . Bilge pump plunger
- Pumplinks
- Flange for connecting injection pipe

**Figure 202:** Diagram of part of an engine, showing cylinder, circulating pump, etc (Paasch 1890: Plate 53)



Figures 203 - 204: Both sides of possible condenser door (Photos: Maitland)



Figures 205 - 206: Views of internal structure of the condenser, the condenser tubes probably fitted through the holes (Photos: Maitland)



Pump leverPump linksBilge pump plungerFigures 207 - 208:Views of the main section of bilge pump (Paasch 1890: Plate 53; Bauer 1905: 321;<br/>Photos: Maitland)



**Figure 209:** Part of a pump with a name plate — ZUIG ACHTER PIEK (Suck Aft Peak - the Aft peak pump). Probably the engine room valve leading to the boiler water tank, situated in the aft peak (Photo: Maitland)

#### Pumps



**Figure 210:** These name plates read from top to bottom:

- Lens Laadruim B5 (Empty cargo hold ballast tank)
  - Donkey Suction from Ballast Tanks

— Suction No. 1 Tank Port (Werz 2010; Photo: Maitland)



**Figure 211:** An unidentified engine part, there are the remains of a turning wheel on the one end and the two pieces are pivoted. Possibly part of the circulating pump and condenser (Photo: Maitland)



Figure 212: Drain covers (Photo: Maitland)



Figures 213 - 214: Views of a crankshaft lubricating oil pump assembly (Renda 2010; Photos: Maitland)



Figures 215 - 216: Pump gland and casing (Renda 2010; Photos: Maitland)



Figure 217: Mitre wheel on a shaft, possibly part of the steering gear (Photo: Maitland)



**Figure 218:** Close-up of the mitre wheel (Photo: Maitland)



**Figure 219:** Possibly part of the *Karin's* steering gear (Photo: Maitland)



**Figure 220:** Part of the reversing gear (Photo: Maitland)

#### **Electric Generator and Fittings**

The generator was probably connected directly to the engine and supplied electricity throughout the vessel.



**Figure 221:** Electric motor coil (Renda 2010; Photo: Maitland)



**Figure 222:** Electric motor armature (Renda 2010; Photo: Maitland)



**Figure 223:** Dynamo's manufacturer's plate — Sir W.G. Armstrong, Whitworth, & Co Ltd. Elswick Standard D.C. Dynamo.



**Figure 224:** Electric motor casing breather (Renda 2010; Photo: Maitland)

Standard D.C. Dynamo.	
·No.	4360
Туре	
·K.W.	7.1
Amps.	71
Volts	100
R.P.M.	365
Winding	Compound



**Figure 225:** Electric junction box (Branch 1910:154; Photo: Maitland)



**Figure 226:** Electric connector, various female nipples and covers for receptacles and rosettes. The second item from the left is stamped — W. Roazs Patent London (Canadian General Electric 1920: 110; Photo: Maitland)



**Figure 227:** Ceramic electrical connector (Photo: Maitland)



**Figure 228:** Electric earth strap (Renda 2010; Photo: Maitland)



Figure 229: Electric ceramic connector and bayonet light fitting (Photo: Maitland)



Figure 230: Various ceramic electrical connections (Photo: Maitland)



Figure 231: Electric wiring in a metal conduit (Photo: Maitland)



Figure 232: Electric wiring in a flexible conduit (Branch 1910: 108; Photo: Maitland)

#### Propeller

The Karin's propeller was cast in one solid piece. In addition, the vessel carried a spare propeller.



#### Key:

- Coupling flange
- Liner; sleeve; casing
- Key way
- Tail end
- Stuffing box gland
- Stern tube flange
- Stuffing box bulkhead
- Tunnel cock; water service cock
- Water service pipe
- Stern tube
- Stern bush
- Propeller post
- Stern tube nut
- Guard ring
- Propeller bosses
- Propeller blades (movable)
- Propeller blade flange Propeller blade (fixed)
- Figure 233: Diagram of propeller shaft, stern tube, propellers (Paasch 1890: Plate 60)



Coupling flanges Thrust shaft collars **Figure 234:** Thrust shaft (Paasch 1890: Plate 59; Photo: Maitland)



Propeller post Pin Stop nut Propeller **Figure 235:** Aft end of the propeller shaft (Paasch 1890: Plate 60; Pursey 1950: 126; Photo: Maitland)





Propeller Stern tube Brass liner Coupling flange Propeller post Brass bush Shaft

**Figures 236 - 237:** Different perspectives of the propeller shaft (Paasch 1890: Plate 60; Pursey 1950: 126; Photos: Maitland)



Figure 238: The spare propeller (Photo: Maitland)



**Figure 239:** One of the recovered propeller blades (Photo: Maitland)

#### **SC Equipment**



**Figure 240:** The ship's bell. It is not engraved with the vessel's name. There may be a manufacturer's stamp inside; however, the inside is coated with conglomerate (Photo: Maitland)



**Figure 241:** Marine chronometer, engraved with the following — Gowland Maker to the Admiralty Sunderland No.  $\frac{5}{8990}$ 

It is solid brass; has engraved roman numerals; a separate second hand at the bottom and at the top is an up-and-down indicator.

This is marked off in increments of 8 from 0 - 56. Above the 0 is engraved — Up; above the 56 is engraved — Down; in place of the 24 is engraved — Wind. This mechanism in marine chronometers was originally developed in 1774, it counts down the time until the clock needs to be wound up again (Gould 1923: 210; Photo: Maitland).



**Figure 242:** Advert from Christie's Shipping Register, Maritime Compendium and Commercial Advertiser (1858). There were eleven Gowland family members that were watchmakers; from Robert Gowland who was active in the 1750s until George Gowland died in 1884 (www.ecodeltempo.altervista.org).

Karin Wreck Report / The Construction / Page 61



**Figure 243:** Mounted Walker's Cherub taffrail log with attached rotator and governor (Photo: www.prices4antiques.com)



**Figure 244:** The *Karin's* taffrail log and governor. The plate is engraved with — Walker's Cherub Ship Log T.W. (Mark II) 900.

The dial is marked around the edges from 0 - 100 which represent miles. The brass hand represents the miles run. The rotator (not recovered) is towed by a patent log line that revolves according to the speed of the ship. The governor is attached to the line, just abaft the rail and helps to make the log work at a uniform speed (Brown 1931: 137; Photo: Maitland)



**Figure 245:** Plano-convex lens of a brass telescope or binoculars (www.wikipedia.org; Photo: Maitland)



**Figure 246:** Standard socket rowlock, probably from the *Karin's* lifeboat (Carpenter 1917: 988; Photo: Maitland)



**Figure 247:** Non-ferrous blade, possibly from a ventilating fan (Photo: Maitland)

### The Equipment and Supplies of the



## S.S. Karin

#### Ship's Tools





Boat clamp Cold chisels Punch Valve spanner Tool grinder handle Tool handle Reversible spanner Blacksmith's tongs

**Figure 248:** Various tools (Carpenter 1917: 83, 192, 886; Photo: Maitland)



Ring spanner Engineer's wrenches Iron work skidding tongs Coal shovel Chisel scraper

Blacksmith's tongs Monkey wrenches

Square head wrench for cocks

**Figure 249:** Fire hooks or valve hooks (Carpenter 1917: 284, 447; Photo: Maitland)



Deck punch Stilson wrench Blacksmith's sledge

punch Rat tail files ch Tamping bar le Flogging spanner Open end spanners

**Figures 250 - 251:** Various tools (Carpenter 1917: 189, 192, 199, 289, 295, 438, 440, 1021; Renda 2010; Photo: Maitland)



**Figure 252:** Valve spanner (Renda 2010; Photo: Maitland)



Figure 253: Fire hoe head, for boiler work (Carpenter 1917: 447; Photo: Maitland) *Karin* Wreck Report / Equipment and Supplies / Page 64



**Figure 254:** Engineer's hammer (Carpenter 1917: 18; Photo: Maitland)



**Figure 255:** Ship's adze (Carpenter 1917: 22; Photo: Maitland)



**Figure 256:** Chisel end bar (Carpenter 1917: 296; Photo: Maitland)



**Figure 257:** Stencil brush (Carpenter 1917: 787; Photo: Maitland)



Figures 258 - 259: Engineer oilers (Carpenter 1917: 475; Photos: Maitland)



**Figure 260:** Kerosene lantern burners (Carpenter 1917: 417; Photo: Maitland)

#### **Miscellaneous Artefacts**



Figure 261: Shaped wooden artefact possibly part of the lifeboat (Photo: Maitland)



Figure262: Wooden handle (Photo: Maitland)



Figure 263: Coir matting (Photo: Maitland)



**Figure 264:** Coal on the site of the *Karin* (Photo: Subtech)



Figure 265: Leather boots (Photo: Maitland)



Figure 266: Belt (Photo: Maitland)



Figure 267: Frying pan (Photo: Maitland)



**Figure 268:** Forks, dessert spoons and teaspoon. The following photographs are close-ups of the maker's marks from left (Photo: Maitland)



**Figure 269:** Fork engraved with — BP (in a circle), followed by the letters B, S, FR and script engraving — Western Silver. BP = British Plate (Photo: Maitland)



**Figure 270:** Fork engraved with — (...)VONAH SILVER SHEFFIELD — F.M. & Co (Photo: Maitland)

#### **Galley Utensils**



**Figure 271:** Dessert spoon engraved with — AMARANTHINE WT & S. Amaranthine means everlasting (Photo: Maitland)



**Figure 272:** Dessert spoon engraved with — H.F. & Co. — S, in a shield stamp. The S is the town mark for Sheffield. This mark is from H. Fisher & Co. who manufactured items between 1908 and 1973. They had their factory in Sheffield (www.silvermakersmarks.co.uk; Photo: Maitland)



**Figure 273:** Dessert spoon engraved with — A.D. & Co. GEM SILVER. Probably Austin & Dodson, makers of all types of cutlery from 1835 - 1925. Based in Sheffield (Woodhead 1991:14; Photo: Maitland)



**Figure 274:** Teaspoon engraved with — HARRISON & HOWSON ALPHA SHEFFIELD. These manufacturers were also known as Harrison Brothers and Howson, active from 1862 -1919 (www.silvermakersmarks.co.uk;Woodhead 1991: 98; Photo: Maitland)



**Figure 275:** Wooden cutlery handle (Photo: Maitland)



**Figure 276:** Silver lid with maker's mark engraved on underside (Photo: Maitland)



**Figure 277:** Close-up of maker's mark — SWAN (Photo: Maitland)



**Figure 278:** White polished stone, possibly a tabletop (Photo: Maitland)

Stone



**Figure 279:** Side view of the white polished stone, showing varying thicknesses. The fragment on the left has a polished curve cut out (Photo: Maitland)



**Figure 280:** Many of the thinner white slabs had holes drilled vertically and horizontally through them (Photo: Maitland)



**Figure 281:** Grey polished stone, possibly a table top (Photo: Maitland)



**Figure 282:** Side view of the grey polished stone, showing varying thicknesses and bevelled edges Photo: Maitland)

#### **Enameled Artefacts**



**Figure 283 - 284:** Enameling is the process of fusing glass powder onto metal, or ceramic. This process delays the corrosion of metal objects and is more hygienic. Enameling was very popular in the first half of the twentieth century. The artefacts found were mostly just slightly curved pieces. We did find two handles, the handle on the right is probably from a jug (www.wikipedia.com; Photo: Maitland)



#### Figure 285: Various bottle necks

- 1. Shard probably from a Codd bottle
- 2. Aqua glass with a laid on strengthening ring, no seam
- 3. No diagnostic features
- 4. Brown glass with crown top, single seam (Lastovica 1982: 16 19; Photo: Maitland)

#### Glass



#### Figure 286: Various bottle bases

- 1. Green, flat, no pontil mark
- 2. Aqua, inverted
- 3. Brown embossed ..SSON.. ..APERR(E)—..SST..
- 4. Aqua slightly inverted
- (Lastovica 1982: 16 19; Photo: Maitland)

Karin Wreck Report / Equipment and Supplies / Page 70



Figure 287: Various embossed shards

- 1. Blue medicine REGISTERED TRADEMARK MAGNESIA
- 2. Aqua, raised leaves and grapes
- 3. Aqua, rampant lion
- 4. Brown, abstract design
- 5. Thick dark green shard
- 6. Brown, .. EWERIE.. (Breweries)
- 7. Green, —.. ER.. .. M..

(Photo: Maitland)



**Figure 288:** Fragments of porthole and skylight glass (Photo: Maitland)

#### **Ceramic Artefacts**

Tiles

Thick earthernware tiles were found throughout the site. These were probably the original tiles from the *Leksveer*. The polychrome patterns on each tiles would have made a cohesive design when 4 or 16 tiles were placed together.





Figure 289: In-situ tile (Photo: Subtech)

**Figure 290:** There were two different styles of these thick tiles, this one was lighter with more blues and greens. (Photo: Maitland)



Figure 291: The other design has much more red ochre in it (Photo: Maitland)



**Figure 292:** Side view of the tiles, you can see here that the tiles were glazed and not made from precoloured clay, it is also more an underglaze than true glaze (Photo: Maitland)



**Figure 293:** Thin green glazed tiles (Photo: Maitland)



**Figure 294:** Thin white glazed tiles (Photo: Maitland)



**Figure 295:** Dark brown stoneware tiles (Photo: Maitland)



**Figure 296:** The underside of the dark brown stoneware tiles showing adhesive ridges (Photo: Maitland)

#### Stoneware



Figure 297: Stoneware handle (Photo: Maitland)



**Figure 298:** Stoneware shards with an internal white glaze, no diagnostic features (Photo: Maitland)



**Figure 299:** Plain stoneware shards, no diagnostic features (Photo: Maitland)



**Figure 300:** Carbonated drinks, particularly ginger beer was packaged in stoneware bottles. The drink maker's logo was applied to the bottle with underglaze transfer printing (Lastovica 1982: 29; Photo: Maitland)



Earthernware

**Figure 301:** Assortment of decorated shards, the ones on the left are decorated with incisions, slip and glazes. The ones on the right are maker's underglaze transfer prints. Close-up in Figures 302 - 305 (Photo: Maitland)



**Figure 302:** The TT and H entwined in a rope is the trademark of Thomas Twyford. From 1898 the firm was known as Twyford Ltd and was based in Hanley, England (Godden 1991: 629; Photo: Maitland)



**Figure 303:** Blue, underglaze transfer print. All that is recognisable is a garter mark, this element was widely used, in a variety of forms, in many British marks and the company's name or initials would have been in the center (Godden1991:13; Photo:



**Figure 304:** Blue, underglaze transfer print. All that can be discerned is the ribbon (Photo: Maitland)



Figure 305 - 306: Two sides of an earthernware shard; black underglaze transfer print but there is not enough of the trademark to identify (Photo: Maitland)



**Figure 307:** Undiagnostic ceramic shards (Photo: Maitland)



**Figure 308:** While these shards are not diagnostic, their glaze was applied in such a way as to cause tiny bubbles to erupt during firing. This is called a pinhole glaze. I do not know if this was intentional (Photo: Maitland)



Figure 309: Undiagnostic foot rings (Photo: Maitland)



Figure 310: Undiagnostic edges or corners (Photo: Maitland)



Figure 311: Unidentified rims (Photo: Maitland)



**Figure 312:** Close-up of decorated rims - Blue-and white design, blue line, gold line on the rim edge, crenulated and slip dots (Photo: Maitland)



Figure 313: Close-up of raised rims (Photo: Maitland)



Figure 314: Close-up of incised rims (Photo: Maitland)





**Figure 315:** Selection of thick rims (Photo: Maitland)

Figure 316: Close-up of thick rim (Photo: Maitland)



**Figure 317:** Close-up of flatware foot ring with transfer print — ..OTELWARE ...LAND ...FIED. Probably Hotelware England (Photo: Maitland)



**Figure 318 - 319:** Fragments that show a square edged hollow-ware, the maker's mark on the bottom is — Rürfir... probably a German or Dutch manufacturer (Photo: Maitland)



Figure 320: Cup handle (Photo: Maitland)



Figure 321: Threaded ceramic, possibly a pot lid (Photo: Maitland)



Figure 322 - 323: Ceramic with a thick glass layer (Photo: Maitland)

The Cargo of the



# S.S. Karin

Wood

Sugar



**Figure 324:** Possibly the remains of dunnage, which was placed under the cargo to stabilize it (Photo: Maitland)



**Figure 325:** The *Karin* carried a small cargo of "jarrah" wood (Photo: Maitland)



**Figure 326:** Sugar sacks still adhering to the hull plating (Photo: Maitland)



Figure 327: Close-up of sugar sacks (Photo: Maitland)

**Petrol Drums** 



Figure 328: In-situ drum lid (Photo: Subtech)



Figure 329: Compressed drum (Photo: Maitland)



Figure 330: Internal view of drum cap (Photo: Maitland)



Figure 331: External view of drum cap (Photo: Maitland



**Figure 332:** Drum lid with cap missing (Photo: Maitland)



# The Lion

#### Introduction

In 2009 during the Durban Harbour Entrance Widening project, the dredger brought up some metal pieces in the proposed position of the sand trap. On examination, these pieces were deemed to be older than 60 years and thus protected under the National Heritage Resources Act. In order to avoid removing the wreck, the sand trap was moved and no more of the wreck was taken out. These pictures are a record of the artefacts removed.

#### Historical Background of the Lion

I believe this is the wreck of the *Lion*. Firstly, the position of the wreck (See Figure 12); secondly, in Appendix B (228) the Natal Advertiser reports "she (the *Karin*) will automatically disappear in the same way as the sunken Lion". Lastly, the construction of the wreckage is congruent with that of the *Lion*.

The *Lion* was built in 1882 by Thms. I.W. & S.B. Co., a steel or iron twin screw steamer of 141 tons; her dimensions were 101'6" x 19'6" x 8'5". She was employed as a harbour tug. Her home port was London and she was owned by the African Boating Company. On 21 July, Captain Hugh Legg had taken lighters to the Outer Anchorage and on returning, heavy seas drove her onto the concrete blocks of the North Pier. Seven lives were lost. In 1944 a dredger bought her boiler (Maitland: Unpublished Shipwreck Database).



### **Figure 334:** Keel showing centre keelson, intercostal keelson and reversed frames (Paasch 1890: Plate19; Photo: Maitland)

#### The Artefacts



**Figure 335:** Turn of the bilge showing frames and riveted hull plating (Paasch 1890: Plate19; Photo: Maitland)



Figure 336: Wooden hold ceiling (Photo: Maitland)



**Figure 337:** Stern tube and propeller (Paasch 1890: Plate 60; Photo: Maitland)



**Figure 338:** Tunnel shaft bearing and thrust shaft of the propeller (Paasch 1890: Plate 59; Photo: Maitland)



**Figure 339:** Close-up of the brass guard ring of the propeller, stamped — SHARD (Paasch 1890: Plate 60; Photo: Maitland)



**Figure 340:** Connecting rod (Paasch 1890: Plate 58)



Figure 341: Skylight glass (Photo: Maitland)



**Figure 342:** Stockless bower anchor (Paasch 1890: Plate 64; Photo: Maitland)



**Figure 343:** Stockless bower anchor (Paasch 1890: Plate 64; Photo: Maitland)



# Conclusion

From a 2010 archaeological perspective, the *Karin* is neither exciting nor of huge historical significance, she only sank 83 years ago. I spoke to a Capt. Lief Stephen Albert Israelsson in February 2010 and he recalled Capt. Asdal talking about the *Karin* and her sinking. The wreck of the *Karin* is thus within living memory. Unfortunately, the result of this is that her historical importance is underplayed. In addition, her position in the shipping channel, of the busiest port in Africa, meant that the wreck had to be removed quickly and efficiently without the usual archaeological methodology.

The vessel has structural details, as well as insights into the daily lives of the coastal steamer sailors, that are not a part of the written record. The fixed keel was installed after the construction of the vessel and is not drawn on the blueprints. The assortment of cutlery and crockery reflects the crew's simple shipboard life. While these are not earth shattering revelations they colour-in our picture of the past.

The report may contain identification inaccuracies, this is due to time constraints. The conglomeration and the deterioration of the artefacts also hampered identification.

This report does not include all the photographs of the recovered artefacts. I have included all these on the report DVD. They may be of use to future researchers.



# References

#### **Primary Sources**

- Brown, C.H. 1930 (16th ed.). Nicolls's Seamanship and Nautical Knowledge for Secon Mates', Mates' and Masters' Examinations. Glasgow. Brown, Son & Furguson, Ltd., Nautical Publishers.
- Canadian General Electric Co. Limited, Electrical Supplies, Catalogue No. 20. 1920 -21. Toronto. General Offices. Available for downloading at <u>www.archive.org</u>
- Carpenter. Geo. B. Carpenter & Co., Catalogue No. 110. General Supplies & Equipment. 1917. Chicago. In-house publication. Available for downloading at <u>www.archive.org</u>
- Christie's Shipping Register, Maritime Compendium and Commercial Advertiser. 1858. Available for downloading at <u>www.books.google.co.za</u>
- Manual of Seamanship, Volume 1. 1951. London. Her Majesty's Stationary Office.
- McLeod, W.A. (Revised by Capt. A.G.W. Miller). 1944 (1984). The Boatswain's Manual. Glasgow. Brown, Son & Furguson, Ltd., Nautical Publishers.
- Morrison.1895. Illustrated Catalogue and Price List of Steam Gauges etc. Manufactured & For Sale by: The James Morrison Brass Mfg. Co. Toronto. Available for downloading at <u>www.archive.org</u>
- Sailing Directions (Enroute) For East Africa and the South Indian Ocean. Pub. 171. 1986(3<sup>rd</sup> Edition) U.S.A. Defense Mapping Agency Hydrographic/Topographic Center.

#### **Secondary Sources**

- Bauer, Dr. G. 1905. Marine Engines and Boilers. London. Crosby, Lockwood & Son. Available for downloading at <u>www.archive.org</u>
- Bender, Colin. 1988. Who Saved Natal? the Story of the Victorian Harbour Engineers of Colonial Port Natal. Durban. Colorgraphic.
- Branch, Joseph G. 1910. Electric Wiring. Chicago. Chicago Branch Publishing Company.
- Davids, Mila and Schippers, Hans. 2004. Innovations in Dutch Shipbuilding: A Systems of Innovation Approach. In: Business and Economic History Online. Available for downloading at <u>www.h-net.org</u>
- Godden, G.A. 1991. Encyclopaedia of British Pottery and Porcelain Marks. London. Barrie & Jenkins.
- Gould, Robert T. 1923. The Marine Chronometer, Its History and Development. London. J.D. Potter.
- House, David. 2004 (3rd Edition). Seamanship Techniques: for Shipboard and Maritime Operations. Butterworth Heinemann.
- Ingpen, Brian. Unicorn: Navigating New Frontiers. Fernwood Press. In-house publication, kindly given to me by Capt. Israelsson in 2010.
- Ingpen, B.D. 1979. South African Merchant Ships. Cape Town. A.A. Balkema.
- Kooij & van de Laar. 2003. The Raadstad conurbation: a floating metropolis in the Dutch Delta. In: The European Metropolis 1920 2003. Dijk. H.v. (Editor). Available for downloading at <u>www.rjh.ub.rugnl</u>
- Lastovica, Ethleen & Al. 1982. Bottles & Bygones: A guide for South African collectors. Cape Town. Don Nelson.

Pearson, Capt. Tony. 1995. "African Keyport" Story of the Port of Durban. Durban. Accucut Books cc.

- Paasch, Capt. H. 1890 (Reprinted 1977). Illustrated Marine Encyclopedia. Watford, Herts. Argus Books Ltd.
- Pursey, H.J. (1942) 1950.Merchant Ship Construction. Glasgow. Brown, Son & Furguson, Ltd., Nautical Publishers.
- Woodhead, Eileen. 1991. Trademarks on Base-metal Tableware. Canada. National Historic Sites. Available for downloading at <u>www.sha.org</u>

#### **Internet Sources**

www.ecodeltempo.altervista.org Accessed 03-06-2010

www.earth.google.com Accessed 06-2009 and 04-2010

www.miramarshipindex.org.nz Accessed 01-02-2010

www.naval-history.net/WWINavyBritish-Shipbuld01.htm Accessed 01-06-2010

www.prices4antiques.com Accessed 05-2010

Zwama, Roel. <u>www.shiplover.hobby-site.com</u> Accessed 20-01-2010

www.silvermakersmarks.co.uk Accessed 01-06-2010

www.wikipedia.org Accessed 2010

#### **Unpublished Sources**

Donald, Colin. Personal Correspondence.

Levine, M. Unpublished Manuscript.

Maitland, Vanessa. Unpublished Shipwreck Database.

Renda, Peter. 2010. Personal Correspondence.

Werz, Dr. B. 2010. Personal Correspondence.