HEAD OFFICE

FILE NO. 92.003.24

eles

This file is part of the consolidated National Monuments Council filing system implemented on 1 May 1990

For previous correspondence see

×

Old File No. 4/K/A16/4

9/2/003/24 Lower Albany Historical Society 1, Markevlyn Flats, Main Street, PORT ALFRED, 6170 0464-42190 1990 - OF. 20. TOURREFE 9/11/1/009/1. DD. 1990-08-1 ASNALY LILLIE REGIMAL REPRESENTATIVE : EASTERN CAPE N. Me. P. OBox 599. GT. 6140. Dear her Lillie - viz Sterchung Plan Fish Kiver ete Veryglad whet malented I could forward was worth while -Solid not go into details. (is Fult Dache huhrang Post) most of which was used as fill in " it. Stone work for embanknew, The Food River Bridge. For Dache Not having been de claned No/c. long ago -Could you do me a favouer ou 2 counts. 1) - according & your predeceor I Hacchenanie - any Walional Yournent sign book within a Mucipal and had & he exected Said for but that hundpality - J'am going quetty least with The Sign posti derivation If in Batherest the Huncipality Very and their Anshlem - or coals. 11). Could Thank (having lost donce where donce years ago -) all aneas which were in the 1985 cerce flored I stud N'Me is to be proclamica - This includes Kanuga Bapiil Church - Cannon Rocks Steet. Thank you achley. Succenely Thean Callow Nosc. Somer albany. Non Cenalis P.S. a var and in abrand in hads work ave. PTO. D

independent of sportal Warrandows 2 3 -08- 1990 REGIONAL REPRESENTATIVE: EASTERN DAPI STREERVERTEENWOOD, MCD: JUS-and On a Totally separate crice Double DRIFT FORS This is at the site where the wagons ete went on Route To For WILLSHIRE (now Ciskei). Iwas en site Thursday 9th august with a faith, lærge party 60-in all - Bradley Fike Chief Conservation Offices ANDRIES VOSTOO Rende Kesenne was mito me when I gave the hestony of Dourse DRIFT FORT- (Its at This Sourt har Sam Khott Natine Reserve & Double Drift in Tennog Cabe Kerenne heer). Iwas approached because Charles Timber lie. Double Drift Reservel, ? leter Bendestt en Chief Congensvation Officer and in Yorloo Recence had hoped I miger unpress on Waltonal Moumments Convert & Low guids available Apresence a rather special fort which is -in a very Vinerable state - Fort Baoun es dupert. " can only say (as is the case of Kaffir Duft Port,) The Losta aprican Whice really As care & do deep nesearch & preservation. If you need historical fled back Smithalskily help. Viz Double Drift - But Gronel hechster is far more motivated even though not as active Sureciely Guen Callow

REPUBLIEK VAN SUID-AFRIKA PROVINSIALE ADMINISTRASIE VAN DIE KAAP DIE GOEIE HOOP

Hoofdirektoraat van Natuuren Omgewingsbewaring

Telegramadres: Natuur

Ons lêer Our file KNO 16/29

Andries Vosloo Koedoereservaat Privaatsak 1006 GRAHAMSTAD 6140



The Regional Representative National Monuments Council P O Box 599 Grahamstown 6140

Attention: Mr A Lilliy

Dear Sir



DOUBLE DRIFT FORT

I refer to your visit to the above site today, and the discussions held pertaining to the preservation of this structure.

May I urge that consideration be given to this Fort with respect to implementing measures in order to prevent the possible collapsing, to lesser or greater degree, of the structure in the foreseeable future.

Envisaged is the installation of wall braces or collars to prevent further crack widening and deterioration, but this will be entirely subject to a Structural Engineers recommendations.

Any consideration which you are able to give to this case will be appreciated.

Yours faithfully

B FIKE OFFICER-IN-CHARGE

Afskrif vir inligting RNG (Oos-Kaap) Copy for information NMC (Eastern Cape)

and an and a second a second

13-10-1990

REGIONAL ALPROJECT ACTUE: ENOTERING APE STATENVENTERING OUT COLOR COMPANY

OF THE CAPE OF GOOD HOPE

PROVINCIAL ADMINISTRATION

Chief Directorate of Nature and Environmental Conservation

Telegraphic Address: Natuur

Telefoon Telephone 0461-27909

Andries Vosloo Kudu Reserve Private Bag 1006 GRAHAMSTOWN 6140

26 September 1990

REPUBLIC OF SOUTH AFRICA



RAAD VIR NASIONALE GEDENKWAARDIGHEDE * NATIONAL MONUMENTS COUNCIL

MEMORANDUM

TO: Architect North

FROM: Regional Manager Eastern Cape

REF: 9/2/003/24

DATE: 8 December 1992

SUBJECT: FORT DOUBLE DRIFT, ANDRIES VOSLOO KUDU RESERVE, ALBANY DISTRICT

- 1. My apologies for infringeing on your time and asking advice, yet again.
- 2. Attached please find photographs of the above fort.
- 3. This complex was erected by the Military Garrison in the mid nineteenth century. It is built of local stone. The complex is effectively ruined. The fort lies about two hundred metres from the Great Fish River and is occasionally covered by flood waters which accounts for much of the damage.
- 4. Officials of the CPA Nature Reserve Conservation Department have expressed concern about the future of the tower which is in a state of near collapse and appears to be moving outwards as can be judged from the photographs.
- 5. CPA officials have expressed the opinion that metal braces or cables around the tower may preserve its future for the time being.

\Your opinion on the above matter would be highly appreciated.

JACKSON BRIAN BPNJ/bk

NATIONAL MONUMENTS COUNCIL

ARCHITECT NORTH

INTERNAL MEMORANDUM

TO: Regional Manager: Eastern Cape

FROM: Architect North

REF: 9/2/003/24 DATE: 18 January 1993

RE: FORT DOUBLE DRIFT, ANDRIES VOSLOO KUDU RESERVE, ALBANY DISTRICT

- 1 Your internal memorandum of 8 December 1992 refers.
- 2 From the photographs and description provided (and in the absence of a site visit and any more detailed information) I would agree that some form of metal bracing or cables would help to stabilise the tower, albeit until such time as the tower can be properly restored.
- 3 Careful consideration will have to be given to the manner in which this is done. The braces will have to be adequately constructed to ensure a useful lifespan. I assume that the full restoration of the tower does not enjoy top priority and it is suggested that these "temporary" braces should be designed to have a substantial life-span in the order of 10-15 years. The manner in which the braces are installed will also have to be carefully considered to avoid further damage to the tower.
- 4 It is suggested that a structural engineer who is familiar with the structural problems of old buildings be consulted for an appropriate solution and the necessary details - perhaps an engineer employed by the CPA.
- 5 My own intuitive approach would be to form corner brackets of two lengths of angle iron joined with short angle iron cleats and with web stiffeners of flat plate (see sketch attached). Round steel bar - say 20 mm diameter could be used as the tension elements with both ends threaded to allow for tightening. Some sort of "packing" would have to be provided between the steel angle and the stone to take up any unevenness in the wall surface.
- 6 I would be interested to see the final solution that is adopted. Hope the above is of some use to you.

WILLIAM A MARTINSON

WAM/aa

AN01f094.wpf