

## COMMENTS & RESPONSES TABLE

NAME & DATE	COMMENT	RESPONSE
<b>COMMENTS RECEIVED ON NOTIFICATION</b>		
<p>Mrs J. M. Stott Adjacent land occupier 13<sup>th</sup> October 2019</p>	<p>Thank you for dropping off the maps and information re the proposed mining operation. The residence on the portion of West Slopes where you dropped off the forms, has a borehole. We are totally dependent on the borehole for the home use. My concern is the disruption of the water table, and the agitation of the lime sediment. This has already caused a problem with Ross Mine (Shires Quarry) the sediment has been disturbed. To the extent that the geysers at the house have had to have their elements replaced every 6 weeks. And prior to the mining operation the elements lasted between 4 and 5 years. And I have had to install gas heaters to by pass the problem. At my expense. Even though I made the same observation to the previous environmental study done! I did approach Rosmin but they did not offer to help with the installation of the gas systems. They just stated that they were not experiencing any lime build up on their elements! The only other problem is the dust that comes off the dumps, Mr Stott is paraplegic and is permantly at the house. And the dust is a major concern as the prevailing winds are south south westerly (SSW) and are tunnelled up the uMzimkhulu valley. Trust this is what is required for your report. Regards,</p>	<p>Noted. Thank you for you comment.</p> <p>Email response from EnviroPro:</p> <p><a href="#">“We will address your comments within the ‘Comments and Response’ table, as well as include yourself as an Interested and Affected Party (I&amp;AP) during the environmental process.</a></p> <p><a href="#">Do you have the registration number/ identification number of the borehole? We will need this to find all the necessary details to determine whether the proposed mine will have any effect on your borehole.</a></p> <p><a href="#">If you have any additional queries, please do not hesitate to contact me.”</a></p> <p>Water quality of the borehole has been addressed within the Draft BAR (Table 8, Section 19).</p>
<b>COMMENTS RECEIVED ON DRAFT BASIC ASSESSMENT REPORT</b>		

## Rowan Buhrmann

---

**From:** Jo Stott <jo.stott@vodamail.co.za>  
**Sent:** 17 October 2019 13:19  
**To:** 'Rowan Buhrmann'  
**Subject:** RE: African Lime Quarry (10628MP)2

Good Afternoon Rowan,  
Thank you for your reply.  
The farm was purchased by the mine (Shires Quarry).  
And I am leasing the house from them and as far as I know we do not have a borehole number.  
Regards,  
Jo Stott (Mrs)  
082 649 0910

---

**From:** Rowan Buhrmann [mailto:rowan@enviropro.co.za]  
**Sent:** 14 October 2019 03:29 PM  
**To:** '27826490910'  
**Cc:** 'Margate Airport'  
**Subject:** RE: African Lime Quarry (10628MP)2

Good afternoon Mrs Stott,

I trust you are well and had an enjoyable weekend.

Thank you again for talking with me on Friday last week.

We will address your comments within the 'Comments and Response' table, as well as include yourself as an Interested and Affected Party (I&AP) during the environmental process.

Do you have the registration number/ identification number of the borehole? We will need this to find all the necessary details to determine whether the proposed mine will have any effect on your borehole.

If you have any additional queries, please do not hesitate to contact me.

*Kind Regards*



**ROWAN BUHRMANN**  
ENVIRONMENTAL CONSULTANT

**C:** 078 558 1124  
**T:** 031 765 2942  
**F:** 086 549 0342  
**E:** [rowan@enviropro.co.za](mailto:rowan@enviropro.co.za)

[www.enviropro.co.za](http://www.enviropro.co.za)

IN ASSOCIATION WITH INKANYEZI YETHU

EnviroPro Environmental Consulting (Pty) Ltd 2017/477958/07 Directors: J. Oberholzer & I. Jourdan  
Shareholders: J. Oberholzer, I. Jourdan & Inkanyezi Yethu I Vat No.: 4320256334 I BEE Level 2

---

**From:** Margate Airport <[MargateAirport@rnm.gov.za](mailto:MargateAirport@rnm.gov.za)>

**Sent:** 13 October 2019 12:57

**To:** [rowan@enviropro.co.za](mailto:rowan@enviropro.co.za)

**Cc:** 27826490910 <[27826490910@vodamail.co.za](mailto:27826490910@vodamail.co.za)>

**Subject:** African Lime Quarry (10628MP)2

Good Day Rowan Buhrmann,

Thank you for dropping off the maps and information re the proposed mining operation.

The residence on the portion of West Slopes where you dropped off the forms, has a borehole.

We are totally dependent on the borehole for the home use.

My concern is the disruption of the water table, and the agitation of the lime sediment.

This has already caused a problem with Ross Mine (Shires Quarry) the sediment has been disturbed.

To the extent that the geysers at the house have had to have their elements replaced every 6 weeks.

And prior to the mining operation the elements lasted between 4 and 5 years.

And I have had to install gas heaters to by pass the problem. At my expense.

Even though I made the same observation to the previous environmental study done!

I did approach Rosmin but they did not offer to help with the installation of the gas systems.

They just stated that they were not experiencing any lime build up on their elements!

The only other problem is the dust that comes off the dumps, Mr Stott is paraplegic and is permantly at the house.

And the dust is a major concern as the prevailing winds are south south westerly (SSW) and are tunnelled up the uMzimkhulu valley.

Trust this is what is required for your report.

Regards,

J.M.Stott (Mrs)

Cell 082 649 0910

e-mail [27826490910@vodamail.co.za](mailto:27826490910@vodamail.co.za) (use this e-mail address!)

Thank you.