

1. Upgrading of the fence surrounding Ekland Safaris:



Fencing along the boundary of Ekland Safaris



Culverts installed for the patrol Road along the fence



Main Gate along the N1 Highway

2. Surfacing of existing access roads:



3. Upgrading of Main Lodge and surrounds:

Photos portraying Main Lodge prior to upgrading and refurbishment



Overview of Main Lodge prior to refurbishment



Central Facility prior to upgrading



Back of house prior to upgrading

Main lodge and facilities after upgrading and refurbishment:



Presidential Villa and lifts to provide access other Villa's



Back of House after upgrading and refurbishment



Three of the seven existing accommodation units at Main Lodge



Upgraded central facility



Main Lodge and Presidential Villa viewed from east to west

4. Pienaar Lodge:

Photo portraying Pienaar Lodge prior to upgrading and refurbishment



After upgrading and refurbishment



Upgraded accommodation units



Pienaar Lodge after upgrading



Aerial view of Pienaar Lodge after upgrading

5. Leadwood Lodge

Photo portraying Leadwood Lodge prior to upgrading:



Leadwood Lodge prior to upgrading



Leadwood Lodge after upgrading and refurbishment

6. Sulphur Springs



Sulphur Springs Day Spa (front view)



Sulphur Springs Day Spa (back view)

7. Patel Gate – Security Building



8. Airstrip



Airstrip after resurfacing and widening



Hydroseeded edges being established