PROPOSED REFURBISHMENT AND CONSTRUCTION OF COASTAL INFRASTRUCTURE WITHIN THE KING SABATA DALINDYEBO LOCAL MUNICIPALITY (KSDLM), HOLE IN THE WALL, EASTERN CAPE

DRAFT BASIC ASSESSMENT REPORT PERIOD (16 November 2021 – 7 January 2022)

COMMENTS AND RESPONSES

Name	Organisation		
Margo Reilly	Interested and Affected Party		
Mr Godfrey Mkhululi Mchithakali	DFFE - Environmental Management Enforcement: Oceans and Coast - Regulatory Compliance and Sector Monitoring (RCSM)		

Name and Date	Comment	Response
Date: 18.11.2021 E Mail " M Reilly	I would like to be advised of all further plans for developments at The Hole in the wall with dates of start and estimated dates of completion. On further study of your communication I note that future plans for Hole in the Wall and Coffee bay areas are available for inspection at both above destinations. Please explain, are these the suggested plans which have not as yet been approved/sanctioned by a government department! This decision will then be made after all comments/suggestions by interested parties are taken into consideration? Who might the competent authority be to whom the plans/comments/suggestions are forwarded to?	Thank you for your comment. Please note that the draft layout plans have been submitted to KSDLM for approval. Acer (Africa) Environmental Consultants (ACER) was appointed to undertake the Basic Assessment and Water Use Licence application for the proposed developments and KSDLM will be responsible for the planning/ implementation of the project. Any comments related to the contents of the Basic Assessments may be forwarded to ACER, any further comments regarding the layouts/ proposals for future development may be forwarded to KSDLM for consideration.
Date: 22.11.2021 E Mail - Godfrey Mkhululi Mchithakali - DFFE - Environmental Management Enforcement: Oceans and Coast	Please include the following person on your database: Mrs Thandeka Mbambo xxxxxxx She works for the section that does commenting in Department. I am from the Enforcement directorate Oceans & Coast and we don't do commenting on behalf of the Department as part of our job.	Thank you for your mail received, we will add her to the database.
Date: 02.11.2021 E Mail Margo Reilly – I & AP	As an interested & concerned party I would like the following points raised and minuted on 26 November meeting. Sadly 2.1/2 days' notice does not allow me to attend. PLEASE CONSIDER SUGGESTIONS BELOW BEFORE SPENDING A LOT OF MONEY ON PICNIC SPOTS ETC. ONCE THESE POINTS ARE ATTENDED TO THERE SHOULD BE NO OBJECTION TO FURTHER UPGRADES. 1. THE ABLUTION BLOCK. Built many years ago, never used, vandalised and refurbished twice at great cost. At present goats and rats inhabit this building and it is a health hazard with broken glass, Rubbish and animal faeces everywhere. Money spent on upgrading should be directed to supplying water to service this building and only then refurbishing it. The main reason for it not being used was no water supply. The water point is approximately 300m above building! When and if ablution Block is once more repaired and has municipal water Cleaners must be employed to look after the facilities. PROPER, CLEAN FUNCTIONING TOILETS ARE ESSENTIAL - BEFORE ANY OTHER IMPROVEMENTS ARE	Thank you for your comments, please refer to the responses below: During the construction phase of the development, a dedicated parking area will be positioned directly next to the existing ablution facilities. At the site visit undertaken on 27 January 2022, the Eastern Cape DEDEAT advised that the Municipality should commission the existing facility for public use as the developments within the area will rely on its functionality.

Name and Date	omment		Response
	UNDERTAKEN. THE STREAM. Running alongside about the street in the stree	mall tree. Builder's rubble, glass and d alongside stream obstructing its flow, his once clean stream, which years ago e are also 4 filthy, unusable, vandalised	Unfortunately, this area falls out of the proposed development at Hole in the Wall. However, the municipality will be advised to promote continuous alien vegetation removal and ensure that the facility is maintained frequently.
	completion. This is an eyesore. As municipal plan was made by residents to deposit collected by municipality. Upgrade mone suitable fenced place in a discrete location building, toilets with no doors, a polluted rubbish. All this is the first thing you see we fact that the entire area is a health hazard	pality does not provide a place for refuse rubbish in old tanks which however is by would be well spent on providing a port. It is unsightly to see this vandalised stream and old tanks holding household when arriving at HIW. Not to mention the	The proposed development will include two new dedicated parking areas and both parking areas will include waste receptacles for the collection and storage of general waste. The municipality will be approached to ensure that funds are made available for the operational phase of the development (which will include regular waste removal).
	VANDALISM. Is a big problem at HIW ar think how many times benches, tables, be and replaced. If you visit the 'picnic' spo bones, bottle tops and all kinds of paper a of path that leads to the forest and Hole	raai and dustbins have been destroyed tabove beach you will find glass, braai	Vandalism is an ongoing issue and this will need to be addressed at a grassroots level. The municipality will be required to undertake cleaning operations and workshops on the importance of maintaining the areas along the coastline.
	CORDONED OFF AREA. An area alor permission) was cordoned off many years the grassy hill. It had taken years to allow repaired and replaced by cottage owners undertaken it is imperative that these be from vehicular use.	s ago to stop vehicles from driving over w the grass to regrow. These posts are s. When these proposed upgraded are	The proposed development at Hole in the Wall includes the introduction of bollards/ barrier caps to prevent vehicles from accessing the coastal grassland. The appointed contractor must ensure that these structures are suitable positioned to prevent vehicular access.
	There are jobless young men who sit are visitors. In the past visitors have been thr on employing, training these youths, pro identify them as guides, car guards, ghilies. This would give them a job and pride in them to keep an eye out for vandalism and	eatened/robbed. Why not spend money vide some sort of uniform which would a and watchmen to check on littering etc. ne work they do and it would encourage	The municipality, with support from the community must allow for the training and regulation of tour guides in the area. The proposed development within the area has the potential to unlock and promote economic growth and this will most often create more jobs for jobless individuals. The municipality is therefore urged to engage with the local community to identify more socio-economic issues which needs to be addressed.

Name and Date	Comment	Response
	7. COMMUNITY LIGHT. A so called community light was erected (badly) next to toilet block. Instead of putting it near the clinic and soccer field to best serve community, it was put behind cottages all of which have electricity and flood lights! It is very expensive and to date has no "light bulbs" has never been brought in to service? With Eskom's problems this light takes far too much power and is a very costly white elephant.	The proposed development at Hole in the Wall will also include the introduction of streetlights within the node. Once installed, the municipality will be responsible for its maintenance. The status of the existing lights fall under the jurisdiction of the municipality and they will be requested to provide comment.
	ANOTHER REASON TO PLAN CAREFULLY AND PRIORITISE MOST NECESSARY UPGRADES BEFORE UNDERTAKING THOSE THAT CAN WAIT.	