

VISITORS CENTER ADDENDUM



1. Restore/Repair concrete sills



2. Replace broken window panes & Re-putty all problematic windows



3. Replace broken asbestos gutter with fiber cement approx. 3 linear Meters



4. 7m x 14m shade cloth 80 % proof with inner steel structure galvanized, to attach to existing pole structure.