



PHOTOGRAPH 21 ---- SEWER PIPE IS EXPOSED - LAID AT PAVING LEVEL WITH PIPE FALLING IN TWO DIFFERANT DIRECTIONS



PHOTOGRAPH 22 ---- SEWER PIPE IS EXPOSED - CONNECTION BETWEEN TWO PIPES INCORRECT
THERE IS A HUG GAP THAT WILL ALLOW FOR THE SEWER TO LEAK ONTO THE PAVING

SIGNATURE
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051
TELEPHONE : 0826644644

91 BEREA PARK