



PHOTOGRAPH 27 ---- EXISTING CONCRETE ROOF SLAB HAS DAMPNESS PROBLEMS



PHOTOGRAPH 28 ---- VIEW OF EXISTING TENNIS COURT IN A DILAPIDATED STATE

SIGNATURE
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051
TELEPHONE : 0826644644

91 BEREA PARK