



PHOTOGRAPH 15 ----- VIEW OF EXISTING ROOF THAT HAS FALLEN IN
(REFER TO PHOTO BELOW FOR TOP VIEW)



PHOTOGRAPH 16 ----- VIEW OF PART OF THE ROOF THAT HAS COLLAPSED - AREA IS COVERED WITH
SOME SORT OF MATERIAL - ENTIRE ROOF IS BORER INFESTED

SIGNATURE
architectural studio

UNIT 24 CANFORD PARK, 53 ANTHONY ROAD, DURBAN NORTH, 4051
TELEPHONE : 0826644644

91 BEREAS PARK