

EXARRO SUBLIME ACCESS ROAD UPGRADE PHOTOGRAPH PLATE

Figure 1: View of Sublime Access Road heading towards the Matla Colliery



Figure 2: View of the condition of the existing road



Figure 3: View of Matla Power Station



Figure 4: View of Vegetation near Sublime, R580 road interchange



Figure 5: Cultivated fields running alongside the Sublime Access Road



Figure 6: View of wetland that the existing Sublime Access Road crosses.



Figure 7: View of Typical Wetland Vegetation found along the Existing Sublime Access Road