Page 1 of 3
64 Gordon Rd, Morningside
Motivation of Additions and Alterations



Amafa aKwaZulu-Natali 195 Langalibalele Street Pietermaritzburg 3201

05 May 2023

AMAFA REPORT: MOTIVATION FOR ADDITIONS AND ALTERATIONS TO EXISTING HOTEL BUILDING

64 GORDAN ROAD, MORNINGSIDE - REM OF ERF 745

The following is a motivation to AMAFA for an Additions and Alteration approval permit for: the enclosure of balconies of an existing Union Period style building that is more than 60 years old. The existing building is a three-story hotel located on 64 Gordon Road, Durban. We have been appointed as the architectural professional and in this regard, we act on behalf of our client Montrose Trust (IT789/2011) and hereby make the following representation in respect to the heritage significance of the property under review.

SITE DETAILS

PROPERTY / STREET ADDRESS: 64 GORDAN ROAD

DATE OF CONSTRUCTION: Original structure 1936 / Newer buildings 2009

ERF NO: REM OF ERF 745 OF DURBAN LOCAL MUNICIPALITY: Ethekwini Municipality CURRENT ZONING: GENERAL RESIDENTIAL 1

PRESENT USE: HOTEL

HISTORIC REPORT

The original date of construction can be traced to 1936 after enquiring with Ethekwini Microfilm Division, however the building is not listed. Having analysed the spatial planning of the building, it is assumed the original building was an apartment building or served a residential type application. The building consists of a three-storey Union Period styled structure. There is a newer two-storey structure, constructed circa 2009, that stands at the rear of the site, in the form of two wings, independent of the original architecture. The newer structure is finished in smooth plaster and paint with aluminium windows. The original structure has a red facebrick plinth, with plastered and painted walls, and reveals of windows and doors painted red.

Records available show alterations to the existing building circa 2009. Records indicate that there were primarily internal alterations with the external work including the closure of a door/ new door repositioned, closure of 4 windows and the construction of a new walkway from the existing building to the newer structure. Apart from an external door being sealed,

Page 2 of 3
64 Gordon Rd, Morningside
Motivation of Additions and Alterations

there were no changes to the façade of the building. Hence, the aesthetic of the building remains unchanged.

ARCHITECTURAL SIGNIFICANCE

The Union Period style architecture of the building features a hipped Marseilles tiled roof, a facebrick plinth, cottage paned windows, panel style balustrade walls, and quoined columns at the corners of the building. Sitting prominently at the fore of the building is the sweeping staircase leading to the main entrance of the structure.

URBAN SETTING AND ENVIRONMENTAL SIGNIFICANCE

The site is situated opposite the Gordon Road Girls School after the Rosetta Road intersection. It is surrounded by existing residential developments, mostly consisting of dwelling houses and larger apartment type buildings. The neighbouring properties are of a similar style. The proposed alteration will have no impact on the environment, and neither is the property off any environmental significance.

SOCIAL/SPIRITUAL/LINGUISTIC SIGNIFICANCE

The property is utilised for dwelling/residential purposes. There is no social/ spiritual or linguistic significance.

SCIENTIFIC /TECHNOLOGICAL SIGNIFICANCE

The property compromises of a smooth plaster and grey paint finish with selected elements such as the entrance door and window reveals painted in red. The entrance courtyard has a face brick perimeter wall with metal laser cut signage. Also on the frontage is the building metre room with large painted signage denoting the building address.

SCOPE OF WORK

The scope of work is to enclose all of the road facing balconies. The existing balcony openings have been proposed to be enclosed by windows matching that of the rest of the building. As such, there is no demolition or brickwork required. The enclosure of the existing balconies aims to provide the hotel rooms with greater usable space as the balconies in their existing form are currently underutilised. During periods of harsh rain, the balconies experience driving rains which have resulted in maintenance issues. The closure aims to address the above and also deals with issues of safety and security of the rooms.

Page 3 of 3 64 Gordon Rd, Morningside Motivation of Additions and Alterations

CONCLUSION

The proposed development complies with SANS 10400 and all the local authority regulations and requirements. We trust that this motivation suffices towards a favourable decision and we look to a positive response.

Report prepared by:

Ahmed Olla Professional Architect SACAP Reg No. 24750105